

# OPERATOR MANUAL

MODEL: KUM-HU300



UPDATE: 1010621

# 1. OUTLINE OF MACHINE

## 1-1 APPEARANCE




Fig-1

## 1-2 FEATURES

- (1). This machine is a vertical and horizontal combination milling machine. It is also able to do angular milling, drilling, boring, ect....
- (2). The power and rapid feed movements in X axis are operated by one motor through a feed gear unit.
- (3). The hardened and ground slide way assures that table will stay where it belongs. These symmetrical ways keep the table balanced as well as providing additional contact surface for superior accuracy and rigidity.
- (4). The feed selection levers are positioned in front of the knee to facilitate quick and simple operation.
- (5). Push button lubrication is provided for all three slide ways and can be checked by the narrow slot in front of the table.
- (6). All gears and shafts in the main spindle drive are hardened and ground.
- (7). High quality castings are used throughout ensuring excellent accuracy and finish on the slide way.
- (8). It is easy to change the vertical spindle speed infinitely to suit good machining conditions.
- (9). Quill will automatic feed can do boring.

## 1-3 SPECIFICATION

| KUM-HU300                                    |                   | UNIT: mm 50HZ      |
|--|-------------------|--------------------|
| <b>Table</b>                                 |                   |                    |
| Size (L x W)                                 | mm                | 1270 x 300         |
| T- Slot (W x no. x Pitch)                    | mm                | 16 x 3 x 80        |
| Swivel                                       | ° degree          | 45°                |
| Distance from vertical spindle nose to table | mm                | 0 ~ 390            |
| <b>Travel</b>                                |                   |                    |
| X- axis x Y- axis x Z- axis( Manual)         | mm                | 930 x 400 x 450    |
| X- axis x Y- axis x Z- axis(Automatic)       | mm                | 920 x 380 x 450    |
| <b>Feed</b>                                  |                   |                    |
| Longitudinal feed rate                       | mm / min          | 18 ~ 320 (6 steps) |
| Longitudinal rapid traverse                  | mm / min          | 1040               |
| Cross feed rate                              | mm / min          | 50~1800 VARI.      |
| Cross rapid rate                             | mm/min            | 1800               |
| Vertical feed traverse (OPTI.)               | mm/min            | 30~600 VARI.       |
| Vertical rapid traverse                      | mm / min          | 600                |
| <b>Vertical Spindle</b>                      |                   |                    |
| Spindle nose                                 | Type              | NT4                |
| Spindle speed                                | min <sup>-1</sup> | 45 ~ 1100          |
| Steps  | No.               | 9                  |
| <b>Horizontal Spindle</b>                    |                   |                    |
| Spindle nose                                 | Type              | NT4                |
| Steps  | No.               | 9                  |
| Spindle speed                                | min <sup>-1</sup> | 60 ~ 1440          |
| Distance from center to bottom of ram        | mm                | 175                |
| Distance from center to table                | mm                | 0 ~ 450            |
| <b>Motor</b>                                 |                   |                    |
| Horizontal Spindle                           | HP / kW           | 5 / 3,7            |
| Table longitudinal feed                      | HP / kW           | 3/4 / 0,55kW       |
| Table cross feed                             | HP / kW           | 1/2 / 0,37kW       |
| Table vertical rapid                         | HP / kW           | 1 / 0,746kW        |
| Coolant pump                                 | HP / kW           | 1/8 / 0,1kW        |
| <b>Size</b>                                  |                   |                    |
| Machine (L x W x H)                          | mm                | 2150 x 1750 x 1890 |
| NET weight                                   | kg                | 2550               |
| GROSS weight                                 | kg                | 2700               |

## STANDARD ACCESSORIES:


|                                   |          |
|-----------------------------------|----------|
| COOLANT SYSTEM                    | 1 UNIT   |
| CUTTER ARBOR AND SIEVE            | 1 SET    |
| ADJUSTING TOOLS                   | 1 SET    |
| TOOL BOX                          | 1 PIECE  |
| CHIP TRAY                         | 1 PIECE  |
| DRAW BARS (VERTICAL & HORIZONTAL) | 2 PIECES |
| LEVELING BLOCKS                   | 4 SETS   |
| LEVELING BOLTS                    | 4 SETS   |

## OPTIONAL ACCESSORIES:


SWIVEL-TYPE MILLING VISE  
CLAMPING KIT

## 1-4 EXTERNAL VIEW

TABLE AND SPINDLE DIMENSION



DIMENSION DRAWING



300P371C  
S:1/28

## 2. INSTALLATION


### 2-1 TRANSPORTATION OF THE MACHINE

This machine weight approximate 2550 kgs (5610 lbs) unpack wooden case. Loosen the 4 bolt from the skid. Move the vertical head in vertical position; remove the ram forward to proper position (Fig 2) then lifting machine.

NOTE: Before lifting machine, check machine in steady and safety condition. Also insert clothes or pieces of wood where wires touched. The machine to absorb impacts which may influence of machine.

### 2-2 INSPECTION AND CLEANING

When the machine is delivered, check for damage or shortages in the number of attachments. Then wipe off dirt and protective coating.



## 2-3 FOUNDATION

Before installation, construct a foundation of sufficient thickness (normally 600mm) and pressure-supporting area (depending on the nature of the ground at the installation site) according to the floor plan introduced in (Fig 3). However, if the installation site has a concrete floor of sufficient strength, the construction of a foundation is unnecessary. When installing, achieve leveling by using anchor bolts and wedges or by using a precision level in combination with wedges or leveling blocks.


## 2-4 INSTALLATION

On the bottom of the machine base, dollies are provided at four corners as shown in in (Fig 3). The machine should be balanced on the four points.

## 2-5 MAINTENANCE AND INSPECTION

### (1). PRECAUTIONS FOR OPERATION

- (A) Always supply lubrication oil to designated oiling points before starting. (Table 1) for your reference.
- (B) Confirm that the work and setting jigs do not strike anything before actuating table feed.
- (C) The power table longitudinal feed should not exceed the range limitations of the machine. Always set the automatic reversing dog on both sides within the moving range.



## 2-6 CUTTING OIL

There are two general types of cutting oil, i.e., water-soluble cutting oil and water-insoluble cutting oil, and these are further divided into many groups. As selection of the cutting oil depends on each cutting condition, particular trade names or groups cannot be specified here but it is necessary to observe the following:

(1) Use of water-insoluble cutting oil

Examples: (A) General purpose cutting oil

(B) Semi Synthetic soluble cutting fluid

(it needs to add water, and the proportion is 1: 20 (oil : water) )

(C) Synthetic soluble cutting fluid

(it needs to add water, and the proportion is 1: 20 (oil : water) )

(2) Capacity of the cutting oil tank is about 8 gallon.

(3) Cutting oil should be supplied through an oil strainer into the cutting oil intake provided on the lower part of the column.

## 2-7 Wiring

The power cord should be connected to the terminals L11, L12, L13 . On completion of the connection, turn on the power switch (Fig 4-1) located on the side of the power box.

After finishing the above preparations, start the main spindle. (See section for spindle starting, spindle stopping and spindle brake). If the rotation direction of the main spindle is clockwise, connections are correct. If rotation is counter-clockwise, exchange connections of two of the three wires L1, L2, L3 of the power cord.

## 2-8 Lubrication

Prior to starting, each moving part must be lubricated with suitable lubricating oil. Refer to table. I for instructions to lubricate the spindle head gears, quill and slide ways.

The lubrication oil to be used for each part is also listed in (Tables 2, and 3), it can be used for selecting the correct lubricant to keep the machine in its best condition.





Fig-4

TABLE -1  
LUBRICATION INSTRUCTIONS



S:1/24  
3000P378

|                    | Spindle gears (V) |         |        | Table feed gears |         |        | Spindle gears(H) |         |        | Arbor support |        |       | Slide ways |  |
|--------------------|-------------------|---------|--------|------------------|---------|--------|------------------|---------|--------|---------------|--------|-------|------------|--|
| Machine components | 2                 | 3       | 4      | 5                | 6       | 7      | 8                | 9       | 10     | 11            | 12     | 13    | 14         |  |
| Check              | Daily             |         |        | Daily            |         |        | Daily            |         |        | Daily         |        | Daily |            |  |
| Fill               |                   | Monthly |        |                  | Monthly |        |                  | Monthly |        |               | Weekly |       | Weekly     |  |
| Clean & Replace    |                   |         | Yearly |                  |         | Yearly |                  |         | Yearly |               |        |       |            |  |
| Lubricant          | CB68              |         |        | CB68             |         |        | CB68             |         |        | G68           |        |       | G68        |  |
| Capacity           |                   | 4L      |        |                  | 40L     |        |                  | 40L     |        |               | 0.5L   |       | 2L         |  |
| Remarks            |                   |         |        |                  |         |        |                  |         |        |               |        |       |            |  |



# INSTRUCTION FOR CORRECT LUBRICANT

TABLE -2


|                   | Application   | Fuels | Properties  | Symbol and Viscosity Grade | Kinematic Viscosity CST (130°F) |           |      | REMARKS  |
|-------------------|---|-------|---|----------------------------|---------------------------------|-----------|------|--|
|                   |   |       |   |                            | Mean                            | min.      | max. |  |
| GEARS             | Enclosed moderately loaded gear (spur gear, bevel gear) |       | Refined mineral oils with good oxidation stability  | CII 32                     | 32                              | 28.8      | 35.2 | Pinion speeds (motor output)<br>2,000 – 5,000 rpm (within 5HP)<br>1,000 – 2,000 rpm (within 10HP)<br>– 1,000 rpm (within 20HP) |
|                   |   |       |   | CII 68                     | 68                              | 61.2      | 74.8 |  |
|                   |   |       |   | CII 150                    | 150                             | 135       | 165  |  |
|                   | Enclosed heavily loaded gears (worm and wheel)          |       | Refined oils with good oxidation stability and with improved load-carrying ability            | CC 150                     | 150                             | 135       | 165  | Worm speeds<br>2,000 – rpm<br>1,000 – 2,000 rpm<br>– 1,000 rpm   |
|                   |   |       |   | CC 320                     | 320                             | 288       | 352  |  |
|                   |   |       |   | CC 460                     | 460                             | 414       | 506  |  |
| BEARINGS          | Spindles bearings and associated clutches               |       | Refined mineral oils with superior anti-corrosion and anti-oxidation performances.            | FC 2                       | 2.2                             | 1.08      | 2.42 | Shaft speeds (shaft dia.)<br>10,000 – rpm ( 1/8 in)<br>2,000 – 10,000 rpm (1/8 – 5/8in)<br>– 2,000 rpm (5/8in)                 |
|                   |   |       |   | FC 10                      | 10                              | 9.00      | 11.0 |  |
|                   |   |       |   | FC 22                      | 22                              | 19.8      | 24.2 |  |
| SLIDEWAYS         | Slide ways  |       | Refined mineral oils with improved lubricity and tackness performance preventing stick-slip   | G 68                       | 68                              | 61.2      | 74.8 | Slide way (surface pressure)<br>Horizontal (under 57lb/in <sup>2</sup> )<br>Vertical (under 57lb/in <sup>2</sup> )             |
|                   |   |       |   | G 220                      | 220                             | 198       | 242  |  |
| HYDRAULIC SYSTEMS | Hydraulic systems                                       |       | Refined mineral oils with superior anti-corrosion and anti-oxidation performance              | HL 32                      | 32                              | 28.8      | 35.2 | Oil temperature (Rated pressure)<br>0 – 148°F (under 500lb/in <sup>2</sup> )<br>85 – 175°F (under 500lb/in <sup>2</sup> )      |
|                   |   |       |   | HL 68                      | 68                              | 61.2      | 74.8 |  |
|                   |   |       |   | HL 150                     | 150                             | 135       | 165  |  |
|                   | Hydraulic and Slide ways                                |       | Refined mineral oils with superior anti-corrosion, anti-oxidation and anti-wear performances. | HM 32                      | 32                              | 28.8      | 35.2 | Oil temperature (Rated pressure)<br>0 – 148°F (under 2000lb/in <sup>2</sup> )<br>85°F – 175°F (under 2000lb/in <sup>2</sup> )  |
|                   |   |       |   | HM 68                      | 68                              | 61.2      | 74.8 |  |
|                   |   |       |   | HM 150                     | 150                             | 135       | 165  |  |
| GREASE            |   |       | Refined mineral oils of HM type with anti-stick-slip properties                               | HG 32                      | 32                              | 28.8      | 32.2 | Oil temperature (Rated pressure)<br>0 – 148°F (under 1000lb/in <sup>2</sup> )<br>85°F – 175°F (under 1000lb/in <sup>2</sup> )  |
|                   |   |       |   | HG 68                      | 68                              | 61.2      | 74.8 |  |
|                   |   |       |   | XM 1                       | 310 – 340                       | 285 – 295 |      |  |
|                   |   |       | Pigment quality greases with superior anti-oxidation and anti-corrosion properties            | XM 2                       | 285 – 295                       |           |      | Centralized systems<br>Cup or hand gun   |
|                   |   |       |   |                            |                                 |           |      |  |

THE GENERAL LUBRICANTS FOR MACHINE TOOL

TABLE -3


|                  | SYMBOL | CPC                        | ESSO/EXXON     | SHELL            | MOBIL                | DAPHNF                   |
|------------------|--------|----------------------------|----------------|------------------|----------------------|--------------------------|
| Gears            | CB 32  | R 32                       | Teresso 32     | Tellus Oil C 32  | DTE Oil Light        | Mechanic Oil 32          |
|                  | CB 68  | R 68                       | Teresso 68     | Tellus Oil C 68  | DTE Oil Heavy Medium | Mechanic Oil 68          |
|                  | CB 150 | R 150                      | Teresso 150    | Tellus Oil C 150 | DTE Oil Extra Heavy  | Mechanic Oil 150         |
|                  | CC 150 | R 150                      | Spartan EP 150 | Omala Oil 150    | Gear 629             | CE Compound 150S         |
|                  | CC 320 | R 320                      | Spartan EP 320 | Omala Oil 320    | Gear 632             | CE Compound 320S         |
|                  | CC 460 | R 460                      | Spartan EP 460 | Omala Oil 460    | Gear 634             | CE Compound 460S         |
| Bearings         | FC 2   |                            |                | High spin oil C2 | Velocite Oil No. 3   | Mechanic Oil 2           |
|                  | FC 10  | R 12                       | Spinesso 10    | Tellus Oil C 10  | Velocite Oil No. 6   | Mechanic Oil 10          |
|                  | FC 22  | R 22                       | Spinesso 22    | Tellus Oil C 22  | Velocite Oil No. 10  | Mechanic Oil 22          |
| Slide Ways       | G 68   | Slide way oil              | Febis K 68     | Tonna T 68       | Vactra Oil No. 2     | Multiway 68C             |
|                  | G 220  | Slide way oil              | Febis K 220    | Tonna T 220      | Vactra Oil No. 4     | Multiway 220C            |
| Hydraulic System | HL 32  | R 32                       | Teresso 32     | Tellus Oil C 32  | DTE Oil Light        | Hydraulic Fluid 32       |
|                  | HL 68  | R 68                       | Teresso 68     | Tellus Oil C 68  | DTE Oil Heavy Medium | Hydraulic Fluid 68       |
|                  | HM 32  | 32 AW                      | Nuto HP 32     | Tellus Oil 32    | DTE 24               | Super Hydraulic Fluid 32 |
|                  | HM 68  | 68 AW                      | Nuto HP 68     | Tellus Oil 68    | DTE 26               | Super Hydraulic Fluid 68 |
|                  | HG 32  | —                          | Powerex DP 32  | Tonna Oil T 32   | Vactroline Oil 1405  | Multiway 32              |
|                  | HG 68  | —                          | Powerex DP 68  | Tonna Oil T 68   | Vactroline Oil 1408  | Multiway 68              |
| Grease           | XM 1   | Gulfcrown Grease E.P. No.1 | Listan 1       | Alvania Grease 1 | Mobilux EP 1         | Cornex Grease No. 1      |
|                  | XM 2   | Gulfcrown Grease E.P. No.2 | Listan 2       | Alvania Grease 2 | Mobilux 2            | Cornex Grease No. 2      |

# LUBRICATION SYSTEM



| NO | PART NAME                              | SPECIFICATION | QTY |
|----|--|---------------|-----|
| 1  | JOINT OF RATIO DISTRIBUTION CONTROLLER | PSB4          | 9   |
| 2  | NUT                                    | PAN4          | 16  |
| 3  | SLEEVE                                 | PB4           | 24  |
| 4  | DISTRIBUTOR                            | DB-8          | 1   |
| 5  | ALUMINUM PIPE                          | Ø4            |     |
| 6  | OUTSIDE STEEL WIRE SOFT TUBE           | Ø4x500L       | 1   |
| 7  | JOINT OF RATIO DISTRIBUTION CONTROLLER | PSB3          | 1   |
| 8  | JOINT OF RATIO DISTRIBUTION CONTROLLER | PSB5          | 6   |
| 9  | DISTRIBUTOR                            | DA-10         | 1   |
| 10 | SET PLUG                               | PA4           | 8   |
| 11 | T-JOINT                                | PKD4          | 1   |
| 12 | LUBRICATION PUMP                       | SMA-601-15    | 1   |

## LUBRICATION FOR VERTICAL ATTACHMENT



| FREQUENCY                                    | LUBRICATE                                     | LUBRICANT  | QUANTITY                  | LUB. AT                                 |
|--|---|--|---------------------------|---|
| 3 months from installation. 6 months regular | Spur gears, Spiral bevel gears, Ball bearings | Gulf Harmony 53<br>Shell turbo oil 33. Esso Telesstic 52 | Top-up to oil sight level | 1.<br>Drain the dirty lubricant from 2. |
| 3 months                                     | Spindle taper roller bearings                 | Esso Andok C.  | Practical quantity        | 3 and 4                                 |

# 3. Operation

## 3-1 OPERATION PANEL

(A) Electric operation panel for standard Z axis table up-down rapid movement (Fig 6-A)

- 1: Power on & lamp
- 2: Y axis rapid button
- 3: Speed adjuster for Y axis feed
- 4: Y axis feed direction lever
- 5: X axis standby button
- 6: Horizontal start button
- 7: Coolant Pump
- 8: Horizontal spindle stop button
- 9: Z axis rapid down button
- 10: Z axis rapid down button
- 11: Emergency stop button



Fig 6-A

(B) Electric operation panel for option Z axis inverter motor and share one inverter controller with Y axis (Fig-6-B)

- 1: Power on & lamp
- 2: Y & Z axes rapid button
- 3: Speed adjuster for Y & Z axes feed
- 4: Y axis feed direction lever
- 5: X axis standby button
- 6: Horizontal start button
- 7: Coolant Pump
- 8: Horizontal spindle stop button
- 9: Z axis up down feed direction lever
- 10: Emergency stop button




Fig 6-B

### 3-2 OVERARM TRANSVERSE MOVEMENT

The overarm may be moved transversely within a range of about 500 mm.

This cross movement should be carried out in the following manners:

- (1) Loosen the 2 bolts. (Fig 7-5)
- (2) Move the overarm, transversely by turning the pinion rotation shaft (Fig 7-6) with a wrench.
- (3) Retighten the 2 bolts after obtaining the necessary movement to fix the overarm.




Fig 7


### 3-3 CHANGE OF HORIZONTAL SPINDLE SPEED

Move lever (Fig 7-1) to position L.M. OR H depending upon the spindle speed range required, and move lever (Fig 7-2) the position A.B OR C particular speed required.

Main switch (Fig 7-7) can power on/off. Speed changes must not be made while the main motor is running. To facilitate changing spindle speed, stop both main and feed motors by depressing “RED” emergency stop button (Fig 6-10) turn spindle direction switch( Fig 7-3) to position forward or reverse and then intermittently press the green inching button (Fig 7-4) on side of box, at the same time moving lever (Fig 7-1, 7-2 )until the required gears are engaged. It should be noted that as a safety measure the feed motor will automatically stop when the inching button is operated.

### 3-4 PARTS NAME OF MACHINE

1. Vertical attachment
2. X axis feed direction selector
3. X axis clamp lever
4. Y axis hand wheel
5. Y axis clamp lever
6. Y axis hand wheel
7. Knee handle
8. Feed box
9. Feed selection lever A feed selection rod
10. Feed selection lever B hi-low feed selection
11. Longitudinal power and rapid traverse engagement lever
12. Control panel
13. Horizontal spindle speed selection lever



**Fig 8**

## 3-5 OPERATION

### 3-5-1 Operation of manual feeding

Operate longitudinal feed by hand wheel (Fig8-4), cross feed by hand wheel (Fig8-6), and vertical feed by hand lever (Fig 8-7).

If directional engage lever (Fig 8-11) at engagement position, longitudinal manual feed can not be operated.

Chart of rotation of manual feed hand wheel and moving direction of working table.

| Hand Wheel<br>Table  | Rotation<br>Direction<br>(clockwise) | Displacement<br>one<br>division | Scale Collar<br>one<br>revolution |
|----------------------|--------------------------------------|---------------------------------|-----------------------------------|
| Longitudinal<br>Feed | Right hand                           | 0.02 mm                         | 5.00 mm                           |
| Cross feed           | Forward<br>(go far from operator)    | 0.02 mm                         | 5.00 mm                           |
| Vertical feed        | Upward                               | 0.02 mm                         | 2.50 mm                           |

### 3-5-2 Operation of Cross Feed

Unclamp the 2 clamp lever on right side of saddle, and rotate cross hand wheel clockwise or counter clockwise for moving in-out.

### 3-5-3 Operation of table vertical rapid and feed traverse

Unclamping the 2 clamping lever at rear side of knee to loose the knee, first please choose switch for Z axis up-down (Fig 6-9), if move to +Z by pressing rapid button (Fig 6-2) then it can lift up the knee. If move to -Z then it can downward the knee. If want to do cutting feed, then move to +Z by feed speed button (Fig 6-3), then speed will be modified, to clockwise direction speed is fast, to counterclockwise speed is slower.

### 3-5-4 Operation of table longitudinal power feed

Loosen the 2 clamping lever (Fig 8-3) on the table before engaging the auto longitudinal feed.

Push down the engagement lever (Fig 8-11), toward the feed R&L selector (Fig 8-2). Right for right movement and left for left movement.

Lift the engagement lever (Fig 8-11) upward for auto longitudinal rapid traverse according to the feed direction from feed R&L selector (Fig 8-2). Set the engagement level (Fig 8-11) in the middle position for manual feed by hand wheel in left and right side of saddle (Fig 8-4)



### 3-5-5 Choice of feed speed

Feeding speed is dependent on the spindle speed material of work piece tips of cutter and diameter of cutters.

With this machine 6 steps of cutting feed and rapid traverse are carried Out from the feed box (Fig 8-8 )


Move the feed selection rod (Fig 8-9 ) to position A.B.C to choose the right feed. Pull the hi-low feed selector ( Fig 8-10 ) out and push it in for to choose the hi-low speed.

### 3-5-6 Operation of cross feed

1. Select the feed direction lever ( Fig 6-4 ) to needed position. Either or forward or backward.
2. Toward feed engage/disengage lever ( Fig 9-1 ) to auto position for automatic cross feeding.
3. Adjust the correct speed from the speed adjuster ( Fig 6-3 )
4. Put feed engage/disengage lever ( Fig 9-1 ) in manual position for Cross manual movement.




**Fig 9-1**



**Fig 9**

### 3-5-7 Operation of swivel table


First loosen the four nuts where are front and rear of table (Fig 10-1), and then forced rotation saddle (Fig 10-2) can be processed to the required point, and then tighten the four nuts. (Fig 10-3)Slewing angle parameters, each engraved on the seat surface 45 degrees indicates a return to the original zero should be re-proof T-slot table straightness.




**Fig 10**

### 3-5-8 Cover function

1. Before press power on (Fig 6-1), make sure the stretched out arm on both sides of the cover, such as location (Fig11-1), and hanging head cover position (Fig12-1) in order to successfully turn the power on.
2. If the attachment head lifting in the side of the fuselage, attachment head covers shall be shift cam (Fig12-3) need to be adjusted to be pressure logic switch (Fig12-4).
3. If you encounter an emergency situation, such as (Fig11-2 & Fig12-2) will cover the shift, it will automatically cut off power supply.




**Fig 12**



**Fig 11**

### 3-5-9 MOUNTING VERTICAL ATTACHMENT

- (A) Move overarm to the extreme rear position. Keeps the front machine surface aligning with the column surface.
- (B) Remove the vertical attachment from it's bracket and shift to front position.
- (C) Before mounting. Be sure to release the six w 5/8" hex head bolt from the two back plates (B). Remove the two back plates.
- (D) Move in the vertical attachment. Be sure to let the two slots mesh with the two keys on horizontal spindle nose.
- (E) Assemble the two back plates and lock the six w5/8" hex head bolts.
- (F) Lock the upper two w 5/8" hex head bolts to overarm.
- (G) Use M16 L-Key to tight the two M16 set screw. (With brass pad at the front) against the column way to prevent the possible rocking during vertical milling.



## 4. Safety device

### 4-1 Thermal relay

When electric current exceeding the rating, the thermal relay (Fig 13) is actuated automatically to stop the driving motor. If the thermal relay is actuated, locate and correct the cause and reset the thermal relay by pressing the thermal relay reset push button.

### 4-2 Fuse

Fuses (Fig 13) are installed in the control box to protect electric circuits. If the machine does not start operation with the poser source connected and no abnormality is indicated in each safety device, check the fuses. If fuses are blown, remove the cause before replacing the fuse.

























Fig 13

# 5. SYMBOLS

The various movements and corresponding symbols used on this machine are indicated in (Table 4).

**TABLE 4**

| NO. | DESCRIPTION                | SYMBOL  | NO. | DESCRIPTION                                 | SYMBOL  |
|-----|----------------------------|---|-----|---|---|
| 1   | Main spindle               |    | 12  | Rapid feed                                  |    |
| 2   | Revolution per minute      |    | 13  | Power pilot lamp                            |    |
| 3   | Feed amount per revolution |    | 14  | Start                                       |    |
| 4   | Neutral                    |    | 15  | Stop  |    |
| 5   | Main spindle brake         |  | 16  | Emergency stop                              |   |
| 6   | Main spindle without brake |  | 17  | Table feed motor                            |  |
| 7   | Table                      |  | 18  | Cutting oil pump                            |  |
| 8   | Feed (normal)              |  | 19  | Vertical spindle clockwise rotation         |  |
| 9   | Low speed feed             |  | 20  | Vertical spindle counter clockwise rotation |  |
| 10  | Longitudinal feed          |  | 21  | Vertical spindle automatic feed             |  |
| 11  | Vertical feed              |  |     |   |   |

# 6. SUITABLE CUTTERS

## 6-1 CARBIDE CUTTERS

TABLE 5

| MATERIAL                |                                 | FACE<br>MILLS         | SLAB<br>MILLS         | END<br>MILLS          | FULL &<br>HALF<br>SIDE<br>MILLS | SAWS                  | FORM<br>MILLS         |
|-------------------------|---------------------------------|-----------------------|-----------------------|-----------------------|---------------------------------|-----------------------|-----------------------|
| MALLEABLE<br>SOFT/HARD  | FEED PER TOOTH<br>FEET PER MIN. | .005-.015<br>200-300  | .005-.015<br>200-300  | .005-.010<br>200-350  | .005-.010<br>200-300            | .003-.004<br>200-350  | .005-.010<br>175-275  |
| CAST STEEL<br>SOFT/HARD | FEED PER TOOTH<br>FEET PER MIN. | .008-.015<br>150-350  | .005-.015<br>150-350  | .003-.010<br>150-350  | .005-.010<br>150-350            | .002-.004<br>150-300  | .005-.010<br>150-300  |
| 100-150<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .010-.015<br>450-800  | .008-.015<br>450-600  | .005-.010<br>450-600  | .008-.012<br>450-800            | .003-.006<br>350-600  | .004-.010<br>350-600  |
| 150-250<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .010-.015<br>300-450  | .008-.015<br>300-450  | .005-.010<br>300-450  | .007-.012<br>300-450            | .003-.006<br>300-450  | .004-.010<br>300-450  |
| 250-350<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .008-.015<br>180-300  | .007-.012<br>150-300  | .005-.010<br>150-300  | .005-.012<br>160-300            | .002-.005<br>150-300  | .003-.008<br>150-300  |
| 350-450<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .008-.015<br>125-180  | .007-.012<br>100-150  | .004-.008<br>100-150  | .005-.012<br>125-180            | .001-.004<br>100-150  | .003-.008<br>100-150  |
| CI HARD<br>225-350BR.   | FEED PER TOOTH<br>FEET PER MIN. | .005-.010<br>125-200  | .005-.010<br>100-175  | .003-.008<br>125-200  | .003-.010<br>125-200            | .002-.003<br>125-200  | .005-.010<br>100-175  |
| CI MED.<br>180-225BR.   | FEED PER TOOTH<br>FEET PER MIN. | .008-.015<br>200-275  | .008-.015<br>175-250  | .005-.010<br>200-275  | .005-.012<br>200-275            | .003-.004<br>200-250  | .006-.012<br>175-250  |
| CI SOFT<br>150-180 BR.  | FEED PER TOOTH<br>FEET PER MIN. | .015-.025<br>275-400  | .010-.020<br>250-350  | .005-.012<br>275-400  | .008-.015<br>275-400            | .003-.004<br>250-350  | .008-.015<br>250-350  |
| BRONZE<br>SOFT/HARD     | FEED PER TOOTH<br>FEET PER MIN. | .010-.020<br>300-1000 | .010-.020<br>300-800  | .005-.010<br>300-1000 | .008-.012<br>300-1000           | .003-.004<br>300-1000 | .008-.015<br>200-800  |
| BRASS<br>SOFT/HARD      | FEED PER TOOTH<br>FEET PER MIN. | .010-.020<br>500-1500 | .010-.020<br>500-1500 | .005-.010<br>500-1500 | .008-.012<br>500-1500           | .003-.004<br>500-1500 | .008-.015<br>500-1500 |
| ALUM. AL.<br>SOFT/HARD  | FEED PER TOOTH<br>FEET PER MIN. | .010-.040<br>2000 UP  | .010-.030<br>2000 UP  | .003-.015<br>2000 UP  | .008-.025<br>2000 UP            | .003-.006<br>2000 UP  | .008-.015<br>2000 UP  |

Generally lower end of range used for inserted blade cutters, higher end of range for index able insert cutters.

## 6-2 HIGH SPEED STEELS CUTTERS

TABLE 6

| MATERIAL                |                                 | FACE<br>MILLS         | SLAB<br>MILLS         | END<br>MILLS          | FULL &<br>HALF<br>SIDE<br>MILLS | SAWS                  | FORM<br>MILLS         |
|-------------------------|---------------------------------|-----------------------|-----------------------|-----------------------|---------------------------------|-----------------------|-----------------------|
| MALLEABLE<br>SOFT/HARD  | FEED PER TOOTH<br>FEET PER MIN. | .005-.015<br>60-100   | .005-.015<br>60-90    | .003-.010<br>60-100   | .006-.012<br>60-100             | .003-.006<br>60-100   | .005-.010<br>60-80    |
| CAST STEEL<br>SOFT/HARD | FEED PER TOOTH<br>FEET PER MIN. | .010-.015<br>40-60    | .010-.015<br>40-60    | .005-.010<br>40-60    | .005-.010<br>40-60              | .002-.005<br>40-60    | .008-.012<br>40-60    |
| 100-150<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .015-.030<br>80-130   | .008-.015<br>80-130   | .003-.010<br>80-140   | .010-.020<br>80-130             | .003-.006<br>70-100   | .008-.010<br>70-100   |
| 150-250<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .010-.020<br>50-70    | .008-.015<br>50-70    | .003-.010<br>60-80    | .010-.015<br>50-70              | .003-.006<br>50-70    | .006-.010<br>50-70    |
| 250-350<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .005-.010<br>35-60    | .005-.010<br>35-50    | .003-.010<br>40-60    | .005-.010<br>35-50              | .002-.005<br>35-50    | .005-.010<br>35-50    |
| 350-450<br>BR. STEEL    | FEED PER TOOTH<br>FEET PER MIN. | .003-.008<br>20-35    | .005-.008<br>20-35    | .003-.010<br>20-40    | .003-.008<br>20-35              | .001-.004<br>20-35    | .003-.008<br>20-35    |
| CI HARD<br>225-350 BR.  | FEED PER TOOTH<br>FEET PER MIN. | .005-.012<br>40-60    | .005-.010<br>35-50    | .003-.008<br>40-60    | .005-.010<br>40-60              | .002-.004<br>35-60    | .005-.010<br>35-50    |
| CI MED.<br>180-225 BR.  | FEED PER TOOTH<br>FEET PER MIN. | .010-.020<br>60-80    | .006-.015<br>50-70    | .003-.010<br>60-90    | .008-.015<br>60-80              | .003-.005<br>60-70    | .008-.012<br>50-60    |
| CI SOFT<br>150-180 BR.  | FEED PER TOOTH<br>FEET PER MIN. | .015-.030<br>80-120   | .010-.025<br>70-110   | .004-.010<br>80-120   | .010-.020<br>80-120             | .002-.005<br>70-110   | .010-.015<br>60-80    |
| BRONZE<br>SOFT/HARD     | FEED PER TOOTH<br>FEET PER MIN. | .010-.025<br>50-225   | .008-.020<br>50-200   | .003-.010<br>50-250   | .008-.015<br>50-225             | .003-.005<br>50-250   | .008-.015<br>50-200   |
| BRASS<br>SOFT/HARD      | FEED PER TOOTH<br>FEET PER MIN. | .010-.025<br>150-300  | .008-.020<br>100-300  | .005-.015<br>150-350  | .008-.015<br>150-350            | .003-.005<br>150-300  | .008-.015<br>100-300  |
| ALUM. AL.<br>SOFT/HARD  | FEED PER TOOTH<br>FEET PER MIN. | .010-.040<br>300-1200 | .015-.040<br>300-1200 | .005-.020<br>300-1200 | .010-.030<br>300-1200           | .004-.008<br>300-1000 | .010-.020<br>300-1200 |



## 7. PREVENTIVE MAINTENANCE

For securing the accuracy and life of the machine, we offer the following preventive maintenance charts.

| Frequency | Item   |
|-----------|--|
| Daily     | <ol style="list-style-type: none"><li>1. It is necessary to oil each lubrication point before operation.</li><li>2. Check the level of the oil lubrication and fill if necessary.</li><li>3. It is necessary to release the clamps, clean and lubricate the table after operation.</li></ol> |
| Monthly   | <ol style="list-style-type: none"><li>1. Check all the gib and adjust if necessary.</li><li>2. Check all the backlash between screws and nuts , and adjust if necessary.</li></ol>   |
| Quarterly | <ol style="list-style-type: none"><li>1. Check and adjust the machine accuracy.</li></ol>  |

May we suggest that.

Before attempting any maintenance in the interests of safety you isolate the machine electrically and in the interests of efficiency you read the relevant section of this manual.

When ordering replacement parts please quote:

- The machine model name and the machine serial no.  
(Situated above the door on the left hand side of the column.)
- The head serial no.  
(Found on the front of the belt housing.)
- Item number
- Part number
- Description
- Quantity

# 8. TROUBLE SHOOTING

## Trouble Shooting

| TROUBLE                                | CAUSE   | CORRECTION  |
|--|---|---|
| FEED STOP SUDDENLY<br>DURING MACHINING | 1. Overload makes the shear pin shear out.  | 1. Check the overload cause and replace shear pin.                        |
| FEED RATE CHANGE<br>NOT WORK           | 2. The jaw of the two speeds rocker broken.   | 1. Replace the two speeds rocker.   |
| KNEE CANT BE POWER<br>ELEVATED         | 1. Knee is locked on column.<br>2. Over weight of workpiece, fixtures...etc.<br>(Max load capacity : 350 kgs)<br>3. Poor lubrication between Knee and column. | 1. Release lock bolts.<br>2. Use hand elevating.<br>3. Check lubrication. |
| HARD TO CHANGE<br>SPEED OF HORIZONTAL  | 1. Gears not meshed.<br>2. Poor lubrication on spline shaft and gears.  | 1. Use "Inching" button.<br>2. Check lubrication.                         |
| RAPID TRAVERSE OF<br>FEEDBOX NOT WORK  | 1. Wrong motor rotating di-<br>2. Multi-disc clutch worn.<br>3. Rapid traverse shifter worn.  | 1. Reconnect the power supply.<br>2. Adjust clutch.<br>3. Replace shifter |

## Trouble Shooting

| TROUBLE                  | CAUSE   | CORRECTION   |
|--------------------------|---|--|
| CHATTER                  | <ol style="list-style-type: none"> <li>1. Lack of rigidity in the machine, fixtures arbor or workpiece.</li> <li>2. Cutting load too great.</li> <li>3. Dull cutter</li> <li>4. Poor lubrication</li> <li>5. Straight tooth cutter.</li> <li>6. Peripheral relief angle too great.</li> </ol> | <ol style="list-style-type: none"> <li>1. Improve rigidity</li> <li>2. Decrease number of teeth in contact with workpiece.</li> <li>3. Resharpen</li> <li>4. Improve lubrication</li> <li>5. Use helical tooth cutter.</li> <li>6. Decrease relief angle</li> </ol>    |
| CANNOT HOLD SIZE         | <ol style="list-style-type: none"> <li>1. Cutting load too great</li> <li>2. May be due to chip packing</li> <li>3. Chips causing misalignment.</li> </ol>  | <ol style="list-style-type: none"> <li>1. Decrease number of teeth in contact with workpiece</li> <li>2. Increase oil pressure in redirect flow so as to wash chips out of teeth</li> <li>3. Brush or blow all chips away before mounting new piece of work</li> </ol> |
| PREMATURE CUTTER DULLING | <ol style="list-style-type: none"> <li>1. Cutting load too great</li> </ol>   | <ol style="list-style-type: none"> <li>1. Decrease number of teeth in contact with workpiece</li> <li>2. Add blending oil to lubricant</li> </ol>  |
| POOR SURFACE FINISH      | <ol style="list-style-type: none"> <li>1. Feed too high</li> <li>2. Dull tool</li> <li>3. Speed too low</li> <li>4. Insufficient number of cutter teeth</li> </ol>  | <ol style="list-style-type: none"> <li>1. Decrease feed and increase speed</li> <li>2. Resharpen</li> <li>3. Increase surface speed</li> <li>4. Use cutter with more closely spaced teeth</li> </ol>   |

## Trouble Shooting


| TROUBLE             | CAUSE  | CORRECTION  |
|---------------------|--|---|
| CUTTER<br>"HOGS IN" | <ol style="list-style-type: none"> <li>1. Peripheral relief too great</li> <li>2. Rake angle too large</li> <li>3. Improper speed</li> </ol> | <ol style="list-style-type: none"> <li>1. Use recommended angle</li> <li>2. Decrease rake angle</li> <li>3. Check and adjust</li> </ol>   |
| VIBRATION           | <ol style="list-style-type: none"> <li>1. Insufficient clearance causing rubbing</li> <li>2. Machine at fault</li> </ol>                     | <ol style="list-style-type: none"> <li>1. Use recommended clearance angle</li> <li>2. Check machine, be sure arbor is at least <math>\frac{1}{3}</math> diameter of cutter</li> </ol> |
| WORK<br>BURNISHING  | <ol style="list-style-type: none"> <li>1. Cut is too light</li> <li>2. Insufficient peripheral relief</li> <li>3. Land too wide</li> </ol>   | <ol style="list-style-type: none"> <li>1. Increase depth of cut</li> <li>2. Increase peripheral relief angle</li> <li>3. Decrease width of land</li> </ol>                            |
| CUTTER<br>BURNS     | <ol style="list-style-type: none"> <li>1. Insufficient lubricant</li> <li>2. Speed too fast</li> </ol>                                       | <ol style="list-style-type: none"> <li>1. Add more sulfur base oil</li> <li>2. Decrease speed</li> </ol>  |
| TEETH<br>BREAKING   | <ol style="list-style-type: none"> <li>1. Feed too high</li> </ol>   | <ol style="list-style-type: none"> <li>1. Decrease feed per teeth May be possible to maintain rate by increasing the number of teeth</li> </ol>                                       |

## 9. SPARE PARTS

When ordering replacement parts please quote:

- The machine model name and the machine serial no.  
(Situating above the door on the left hand side of the column.)
- Item number
- Part number
- Description
- Quantity
- PARTS OBTAINABLE IN INCH(I) OR METRIC(M)


# VERTICAL ATTACHMENT



## VERTICAL ATTACHMENT


| NO | NAME                           | NO | NAME                     |
|----|--------------------------------|----|--------------------------|
| 1  | NUT                            | 42 | LOCK NUT AN05            |
| 2  | TAPER PIN                      | 43 | SELF LOCK WASHER AW05    |
| 3  | NUT                            | 44 | HEAD SEAT                |
| 4  | PULL STUD                      | 45 | PLATE                    |
| 5  | SOCKET SCREW M6x40             | 46 | BALL BEARING 6204        |
| 6  | TOP COVER                      | 47 | GEAR                     |
| 7  | SOCKET SCREW M6x20             | 48 | BALL BEARING 6207        |
| 8  | SET SCREW                      | 49 | OIL SEAL, V-TYPE 45,65,5 |
| 9  | TAPPER ROLLER BEARING #32210   | 50 | COVER                    |
| 10 | LOCK NUT AN11                  | 51 | FLAT HD SET SCREW M5x12  |
| 11 | SELF LOCK WASHER AW11Ø55       | 52 | KEY 10x10x23             |
| 12 | SPIRAL BEVEL GEAR              | 53 | JOINT SHAFT              |
| 13 | SET SCREW M8x12                | 54 | BRACKET                  |
| 14 | COLLAR                         | 55 | HEX SCREW W5/8"x1¾"      |
| 15 | HEAD                           | 56 | SPRING WASHER 5/8"       |
| 16 | OIL SEAL, V-TYPE 60,75,10      | 57 | COPPER PAD               |
| 17 | TAPPER ROLLER BEARING #32212   | 58 | SET SCREW M16x25         |
| 18 | OIL SEAL, V-TYPE 89,115,9      | 59 | HEX SCREW 5/8"x3½        |
| 19 | SPINDLE NOSE COVER             | 60 | WASHER                   |
| 20 | SOCKET SCREW M5x15             | 61 | OIL DRAINER 1/4"         |
| 21 | SPINDLE                        | 62 | OIL CAP 5/8"             |
| 22 | KEY 12x8x60                    | 63 | HANG PLATE               |
| 23 | KEY                            | 64 | SPRING WASHER ½"         |
| 24 | LOCKET SCREW M8x20             | 65 | HEX SCREW ½"x1½"         |
| 25 | FRONT COVER                    | 66 | HEX NUT 5/8"             |
| 26 | SOCKET SCREW M6x15             | 67 | TAPPER PIN               |
| 27 | OIL GAUGE                      | 68 | HEX NUT ¾"               |
| 28 | OIL NIPPLE 1/8"                | 69 | HANG BOLT                |
| 29 | KNOCK BOLT #6                  | 70 | YORK                     |
| 30 | HEX NUT 5/16"                  | 71 | SPRING WASHER 3/8"       |
| 31 | T-BOLT                         | 72 | HEX NUT 3/8"             |
| 32 | WASHER                         | 73 | COLLAR                   |
| 33 | HEX NUT 5/8"                   | 74 | BOLT                     |
| 34 | SPIRAL BEVEL GEAR SHAFT 7x4x35 | 75 | SOCKET SCREW M12x20      |
| 35 | KEY                            | 76 | BOOM                     |
| 36 | BALL BEARING #7207             | 77 | SNAP RING                |
| 37 | COLLAR                         | 78 | POST                     |
| 38 | BEARING HOUSING                | 79 | HEAD SWIVELL INDICATOR   |
| 39 | SOCKET SCREW M8x16             | 80 | RIVET Ø2x5               |
| 40 | WASHER                         | 81 | HEAD SWIVELL SCALE       |
| 41 | PINION                         |    |                          |

SADDLE ASSEMBLY  
(HU-300)






# SADDLE ASSEMBLY (HU-300)



# SADDLE ASSEMBLY (HU-300)




3000P375

# HU-300 SADDLE ASSEMBLY

| S/N | P/N      | DESCRIPTION             | S/N | P/N      | DESCRIPTION     |
|-----|----------|-------------------------|-----|----------|-----------------|
| 1   | S-129    | Saddle                  | 45  | S-144    | Bearing Stop    |
| 2   | S-130    | Swivel Base             | 46  | 6004ZZ   | Ball Bearing    |
| 3   | S-135    | Micro Switch Cover      | 47  | S-133    | Shaft           |
| 4   | SP-070   | Nut                     | 48  | S-147    | Spacer          |
| 5   | 300-S136 | Dog                     | 49  | S-143    | Gear            |
| 6   | 300-S137 | Dog                     | 50  |          | Bearing Bracket |
| 7   |          | Spring                  | 51  |          | Spacer          |
| 8   | 1/4      | Steel Ball              | 52  |          | Spacer          |
| 9   | S-114    | Shaft                   | 53  | 6304ZZ   | Ball Bearing    |
| 10  | S-72     | Cover                   | 54  |          | Lock Nut        |
| 11  | S-112    | Lever Bracket           | 55  | 300-T102 | Bearing Bracket |
| 12  | S-113    | Lever                   | 56  | S-153    | Gover           |
| 13  | H-178    | Handle-Knob             | 57  | 6204ZZ   | Ball Bearing    |
| 14  |          | Handle                  | 58  | 6x6x20L  | Key             |
| 15  | AC-30    | Handle Wheel            | 59  | S-97     | Gear            |
| 16  | T-42-1   | Spring                  | 60  | 6204ZZ   | Ball Bearing    |
| 17  | T-58     | Dial                    | 61  | H-47     | Snap Ring       |
| 18  | T-12     | Set Screw               | 62  | T-59     | Dial Holder     |
| 19  | 300-T101 | Bearing Bracket         | 63  | Z-15GD-B | Micro Switch    |
| 20  | M6x25L   | Hex. Socket Head Bolt   |     |          |                 |
| 21  | 6304ZZ   | Ball Bearing            |     |          |                 |
| 22  |          | Bearing Bracket         |     |          |                 |
| 23  | M8x35L   | Hex. Socket Head Bolt   |     |          |                 |
| 24  | 300-T122 | Lead Screw              |     |          |                 |
| 25  | T-53     | Leadscrew Adjusting Nut |     |          |                 |
| 26  | D13-1    | Nut Bracket             |     |          |                 |
| 27  | T-52     | Leadscrew Fixed Nut     |     |          |                 |
| 28  | R-73     | Fixed Bolt              |     |          |                 |
| 29  | S-99     | Spacer                  |     |          |                 |
| 30  | M6x30L   | Hex. Socket Head Bolt   |     |          |                 |
| 31  | 300-S132 | Bearing Bracket         |     |          |                 |
| 32  | S-96     | Gear                    |     |          |                 |
| 33  | H-164    | Lock Nut                |     |          |                 |
| 34  | 300-S131 | Gear Shaft              |     |          |                 |
| 35  | S-93     | Gear                    |     |          |                 |
| 36  | M8x25L   | Hex. Socket Head Bolt   |     |          |                 |
| 37  | #4x30L   | Taper pin               |     |          |                 |
| 38  | S-94     | Gear Bracket            |     |          |                 |
| 39  | 51108    | Thrust Bearing          |     |          |                 |
| 40  | S-121    | Spacer                  |     |          |                 |
| 41  | T-39     | Lock Nut                |     |          |                 |
| 42  | S-134    | Bearing Bracket         |     |          |                 |
| 43  | M6x20L   | Hex. Socket Head Bolt   |     |          |                 |
| 44  | 6204ZZ   | Ball Bearing            |     |          |                 |

# COLUMN KNEE (HU-300)




300P258A

## COLUMN KNEE (HU-300)

| S/N | DESCRIPTION           | S/N | DESCRIPTION           | S/N | DESCRIPTION  |
|-----|-----------------------|-----|-----------------------|-----|--------------|
| 1   | HOOK                  | 39  | SPACER                | 77  | KEY          |
| 2   | ARM                   | 40  | DIAL HOLDER           | 78  | PULLEY       |
| 3   | ARBOR BRACKET         | 41  | BARING STOP           | 79  | LOCK SCREW   |
| 4   | BUSH                  | 42  | HEX. SOCKET HEAD BOLT | 80  | BELT         |
| 5   | SET NUT               | 43  | DIAL RING             | 81  | BALL BEARING |
| 6   | OIL LEVEL GAGE        | 44  | DIAL LOCK NUT         | 82  | GEAR         |
| 7   | BEVEL GEAR            | 45  | HANDLE WHEEL          |     |              |
| 8   | BALL BEARING          | 46  | NUT                   |     |              |
| 9   | SCREW ROD             | 47  | WASHER                |     |              |
| 10  | SET SCREW             | 48  | BEVEL GEAR            |     |              |
| 11  | SET NUT               | 49  | LEED SCREW            |     |              |
| 12  | SHAFT                 | 50  | NUT                   |     |              |
| 13  | BARING SUPPORT        | 51  | LEED SCREW HOUSING    |     |              |
| 14  | SHAFT                 | 52  | BASE                  |     |              |
| 15  | BARING STOP           | 53  | FIXED RING            |     |              |
| 16  | CLUTCH SHAFT          | 54  | HEX. SOCKET HEAD BOLT |     |              |
| 17  | BALL BEARING          | 55  | ORIZONTAL SPINDLE     |     |              |
| 18  | NEEDLE SHAFT          | 56  | KEY                   |     |              |
| 19  | HEX. SOCKET HEAD BOLT | 57  | HEX. SOCKET HEAD BOLT |     |              |
| 20  | CLUTCH SLEEVE         | 58  | CAP                   |     |              |
| 21  | ELEVATING CRANK       | 59  | BALL BEARING          |     |              |
| 22  | HANDLE                | 60  | BALL BEARING          |     |              |
| 23  | LIMITER               | 61  | SPACER                |     |              |
| 24  | LIMITER SET           | 62  | BALL BEARING          |     |              |
| 25  | COVER                 | 63  | SPACER                |     |              |
| 26  | KNEE                  | 64  | MILLING ARBOR         |     |              |
| 27  | GIB                   | 65  | SPACING COLLARS       |     |              |
| 28  | GIB HOLDER-R          | 66  | COLUMN                |     |              |
| 29  | GEAR REDUCER MOTOR    | 67  | COOLANT PUMP          |     |              |
| 30  | LUBRICATION PUMP      | 68  | SHIFT FORK            |     |              |
| 31  | GIB                   | 69  | ROCKING ARM           |     |              |
| 32  | GIB HOLDER-L          | 70  | SHAFT                 |     |              |
| 33  | CHIP GUARD            | 71  | HAND BLOCK            |     |              |
| 34  | ADJUSTING SCREW       | 72  | HEX. SOCKET HEAD BOLT |     |              |
| 35  | NUT                   | 73  | HANDLE ROD            |     |              |
| 36  | LEED SCREW            | 74  | MOTOR BRACKET         |     |              |
| 37  | NUT                   | 75  | HEX. SOCKET HEAD BOLT |     |              |
| 38  | BARING SUPPORT        | 76  | MOTOR                 |     |              |

# COLUMN KNEE (HU-300)




300P258A

# COLUMN KNEE (HU-300)

| S/N | DESCRIPTION           | S/N | DESCRIPTION           |
|-----|-----------------------|-----|-----------------------|
| 83  | SPACER                | 120 | SET NUT               |
| 84  | GEAR                  | 121 | THRUST BEARING        |
| 85  | BALL BEARING          | 122 | BALL BEARING          |
| 86  | SPACER                | 123 | WASHER                |
| 87  | C-RING                | 124 | WASHER                |
| 88  | SHAFT                 | 125 | BALL BEARING          |
| 89  | KEY                   | 126 | BEARING BRACKET       |
| 90  | HEX. SOCKET HEAD BOLT | 127 | HEX. SOCKET HEAD BOLT |
| 91  | HEX. SOCKET HEAD BOLT | 128 | BEARING BRACKET       |
| 92  | CAP                   | 129 | KEY                   |
| 93  | SPACER                | 130 | SHAFT                 |
| 94  | BALL BEARING          | 131 | HEX. SOCKET HEAD BOLT |
| 95  | GEAR                  | 132 | KEY                   |
| 96  | GEAR                  | 133 | DIAL                  |
| 97  | GEAR                  | 134 | LOCK NUT              |
| 98  | GEAR SHAFT            | 135 | SPRING                |
| 99  | GEAR                  | 136 | C-RING                |
| 100 | GEAR                  | 137 | NEEDLE BEARING        |
| 101 | GEAR                  | 138 | SPACER                |
| 102 | KEY                   | 139 | WASHER                |
| 103 | GEAR                  | 140 | COLLAR                |
| 104 | SPACER                | 141 | COVER                 |
| 105 | GEAR                  | 142 | NUT                   |
| 106 | GEAR                  | 143 | HEX. SOCKET HEAD BOLT |
| 107 | LOCK WASHER           | 144 | SHIM                  |
| 108 | LOCK NUT              | 145 | WASHER                |
| 109 | BALL BEARING          | 146 | FIX PLATE             |
| 110 | FLANGE                | 147 | HEX. SOCKET HEAD BOLT |
| 111 | HEX. SOCKET HEAD BOLT |     |                       |
| 112 | LOCK WASHER           |     |                       |
| 113 | LOCK NUT              |     |                       |
| 114 | NUT                   |     |                       |
| 115 | WASHER                |     |                       |
| 116 | DRAWBAR               |     |                       |
| 117 | PULLEY                |     |                       |
| 118 | BRACKET               |     |                       |
| 119 | SPACING COLLARS       |     |                       |



# LONGITUDINAL GEAR BOX






## LONGITUDINAL GEAR BOX

| NO | NEME             | NO | NEME             |
|----|------------------|----|------------------|
| 1  | Body for Gears   | 36 | Hamdle           |
| 2  | Cap Plate        | 37 | Axle Lever       |
| 3  | Cap for Electric | 38 | Spur Gear        |
| 4  | Spur Gear        | 39 | Lever Block      |
| 5  | Bearing          | 40 | Clutch Block     |
| 6  | Link for Gear    | 41 | Lever Block      |
| 7  | Washer           | 42 | Nlain Shaft      |
| 8  | Spur Gear        | 43 | Bushing          |
| 9  | Gear with Clutch | 44 | Flange           |
| 10 | Clutch           | 45 | Hamdle Block     |
| 11 | Cone with Gear   | 46 | Handle           |
| 12 | Main Shaft       | 47 | Gears Block      |
| 13 | Cover Bearing    | 48 | Shaft for Block  |
| 14 | Bearing          | 49 | Flange           |
| 15 | Main Shaft       | 50 | Hamdle for Gears |
| 16 | Spur Gears       | 51 | Motor            |
| 17 | Spur Gears       | 52 | Motor Cover      |
| 18 | Main Shaft       | 53 | Clutch           |
| 19 | Spur Gears       |    |                  |
| 20 | Spur Gears       |    |                  |
| 21 | Main Shaft       |    |                  |
| 22 | Spur Gears       |    |                  |
| 23 | Spur Gears       |    |                  |
| 24 | Main Shaft       |    |                  |
| 25 | Spur Gears       |    |                  |
| 26 | Worm Gear        |    |                  |
| 27 | Bearing          |    |                  |
| 28 | Motor Axle       |    |                  |
| 29 | Motor Flange     |    |                  |
| 30 | Lock Nut         |    |                  |
| 31 | Black for Gears  |    |                  |
| 32 | Lever Black      |    |                  |
| 33 | Gears Axle       |    |                  |
| 34 | Hamdle Cover     |    |                  |
| 35 | Hamdle Screw     |    |                  |

# CROSS FEED (INVERTER MOTOR)



# CROSS FEED

| NO | NAME                 | NO | NAME                 |
|----|----------------------|----|----------------------|
| 1  | Feed Box             | 42 | Hex.Socket Head Bolt |
| 2  | Handle Screw         | 43 | C-Ring               |
| 3  | Fixed Shaft          | 44 | Lock Washer          |
| 4  | Fixed Seat           | 45 | Spring Pin           |
| 5  | Hex.Socket Head Bolt |    |                      |
| 6  | Hex.Socket Head Bolt |    |                      |
| 7  | Handle Seat          |    |                      |
| 8  | Stell Ball           |    |                      |
| 9  | Spring               |    |                      |
| 10 | Clutch Shaft         |    |                      |
| 11 | Handle               |    |                      |
| 12 | Fixed Seat           |    |                      |
| 13 | Plastic Ball         |    |                      |
| 14 | Clutch Sleeve        |    |                      |
| 15 | Key                  |    |                      |
| 16 | C-Ring               |    |                      |
| 17 | Ball Bearing         |    |                      |
| 18 | Belt Wheel           |    |                      |
| 19 | Belt                 |    |                      |
| 20 | Lock Nut             |    |                      |
| 21 | Baring Stop          |    |                      |
| 22 | Spacer               |    |                      |
| 23 | Spacer               |    |                      |
| 24 | Ball Bearing         |    |                      |
| 25 | Ball Screw           |    |                      |
| 26 | Baring Bracket       |    |                      |
| 27 | Baring Bracket       |    |                      |
| 28 | Ball Bearing         |    |                      |
| 29 | Set Screw            |    |                      |
| 30 | Set Screw            |    |                      |
| 31 | Key                  |    |                      |
| 32 | Spring               |    |                      |
| 33 | Clutch Sleeve        |    |                      |
| 34 | Handlet Wheel        |    |                      |
| 35 | Dial                 |    |                      |
| 36 | Baring Stop          |    |                      |
| 37 | Flange               |    |                      |
| 38 | Belt Wheel           |    |                      |
| 39 | Motor Bracket        |    |                      |
| 40 | Cover                |    |                      |
| 41 | Motor                |    |                      |










# KNEE TYPE VERTICAL HORIZONTAL TURRET MILLING MACHINE










## INSPECTION RECORD

Model: \_\_\_\_\_

Mfg. No: \_\_\_\_\_

Date: \_\_\_\_\_

| No. | Test to be applied  |                           | Fig  | Permissible error | Measure value |
|-----|---|---------------------------|--|-------------------|---------------|
| 1   | Leveling of work table  | In longitudinal direction |    | 0.06/1000         |               |
|     |   | In transverse direction   |    | 0.06/1000         |               |
| 2   | Runout of spindle   | In radial direction       |    | 0.01              |               |
| 3   | Longitudinal movement of spindle nose                         | In axial direction        |    | 0.015             |               |
| 4   | Runout of internal taper                                      | Nearest to spindle nose   |   | 0.01              |               |
|     |   | At a distance of 300mm    |  | 0.02              |               |
| 5   | Surface of work table parallel with its longitudinal movement |                           |  | 0.03              |               |
| 6   | Surface of work table parallel with its transverse movement   |                           |  | 0.02/300          |               |
| 7   | Center T-slot parallel with longitudinal table movement       |                           |  | 0.03              |               |
| 8   | Center T-slot parallel with longitudinal table movement       |                           |  | 0.02/300          |               |

| No. | Test to be applied   |  | Fig  | Permissible error | Measure value |
|-----|--|--|--|-------------------|---------------|
| 9   | Column ways for knee square with work table                        | Lateral incline towards front and rear side                          |    | 0.02/300          |               |
|     |  | Incline towards front and rear side, respectively                    |    | 0.02/300          |               |
| 10  | Work table square with cutter spindle in plane                     | Through longitudinal axis (table rising towards the front side only) |    | 0.02/300          |               |
|     |  | Perpendicular to that through longitudinal axis                      |    | 0.02/300          |               |
| 11  | Runout of spindle  | In radial direction  |    | 0.01              |               |
| 12  | Longitudinal movement of spindle nose                              | In axial direction   |   | 0.015             |               |
| 13  | Cutter spindle: Internal taper runs out of truth (use testing bar) | Nearest to the spindle nose  |  | 0.01              |               |
|     |  | At distance of 300mm   |  | 0.02              |               |
| 14  | Work table parallel with Cutter spindle                            | Table rising towards front side                                      |  | 0.02/300          |               |
| 15  | Transverse movement of table parallel with cutter spindle          | In vertical plane  |  | 0.02/200          |               |
|     |  | In horizontal plane  |  | 0.02/300          |               |

| DIRECTOR | INSPECTOR | APPROVED BY |
|----------|-----------|-------------|
|          |           |             |