

HIGH SPEED PRECISION LATHE

MODEL : -1330V (13" x 30")
 -1340V (13" x 40")

INSTRUCTION AND SPARE PARTS MANUAL



Photo shown model : -1340V with front moveable chip tray

SAFETY PRECAUTIONS

1) General Safety Precautions

When operation the machine, think about what you are going to do before you do it.
Go over a safety checklist.

1. Do I know how to operate this machine ?
2. What are the potential hazards involved ?
3. Are all guards in place ?
4. Are my procedures safe ?
5. Am I doing something that I probably should not do ?
6. Have I made all the proper adjustments and tightened all locking bolts and clamps ?
7. Is the workpiece secured properly ?
8. Do I have proper safety equipment ?
9. Do I know where the stop switch is ?
10. Do I think about safety in everything I do ?

Clothing, Hair and Jewelry

Wear a short sleeve shirt or roll up long sleeves above the elbow. Keep your shirt tucked in and remove your necktie. It is recommended that you wear a shop apron. A shop coat may be worn as long as you roll up long sleeves. Do not wear fuzzy sweaters.

If you have long hair, keep it secured properly to avoid your hair being entangled in a moving machine.

Remove your wristwatch and rings before operating the machine. These can cause serious injury if they should be caught in a moving part.

Hand Protection

Use a brush to remove chips. Do not use your hands. Resist the temptation to grab chips as they come from a cut. Chips should not be removed with a rag. The metal particles become imbedded in the cloth and they may cut you.

Gloves must not be worn.

If a glove should be caught in a moving part, it will be pulled in along with the hand inside it.

Various cutting oils, coolants, and solvents may affect your skin. The result may be a rash or possible infection. Avoid direct contact with these products as much as possible and wash your hand as soon as possible after contact.

You may be tempted to blow chips from the machine by using compressed air. This is not good practice. The air will propel metal particles at high velocity. They can injure you or someone on the other side of the machine. Do not blow compressed air on your clothing or skin. The air can be dirty and the force can implant dirt and germs into your skin.

Electrical

If you are adjusting the machine or accomplishing maintenance, you should unplug it from the electrical service. If it is permanently wired, the circuit breaker may be switched off and tagged with an appropriate warning.

2) Turning Machine Safety

The machine can be a safe machine only if the machinist is aware of the hazards involved in its operation. Develop safe work habits in the use of setups, chip breakers, guards and other protective devices. Standards for safety have been established as guidelines to help you eliminate unsafe practice. Some of the hazards are as follows:

1. Pinch points due to movement: Keep your hands away from dangerous positions, such as gears, chuck or rotating cutters.
2. Hazards associated with falling components: Heavy chucks workpieces vises, etc. can be dangerous when accidentally dropped. Care must be used when handling them. A chuck wrench left in the chuck can become a missile when the machine is turned on. Always remove the chuck wrench immediately after using it.
3. Hazards resulting from contact with high temperature components: Burns usually result from handling hot chips or a hot workpiece. Gloves may be worn when handling hot workpiece, but never worn when the machine is running.
4. Hazards resulting from contact with sharp edges, corners, and projections: Shields should be used for protection from flying chips and coolant. These shields are usually made of clear plastic. Stringy chips must not be removed with bare hands, wear heavy gloves and use hook tools or pliers but always turn-off the machine before attempting to remove chips. Chips should be broken rather in a stringy mass or long wire. Chip breakers on tools and correct feeds will help to produce safe, easily handled chips. Burred edges must be removed before the workpiece is removed from the machine. Always remove the tool bit when setting up or removing workpieces to avoid cutting yourself.
5. Hazards of workholding devices: When workpieces are clamped, their components often extend beyond the outside diameter of the holding device. Guards, barriers, and warnings such as signs or verbal instructions are all used to make you aware of the hazards. Never run a geared scroll chuck without having something being gripped in the jaws. Centrifugal force on the jaws can cause the scroll to unwind and the jaws to come out of the chuck. Keep tool, files and micrometers off the machine. They may vibrate off into the revolving chuck or workpiece, or cutter.
6. Spindle breaking: The spindle or workpiece should never be slowed or stopped by hand gripping or any other means. Always use the machine controls to stop or slow it.

7. Workpieces extending out of the lathe should be supported by a stock tube:
If a slender workpiece is allowed to extend beyond the headstock spindle a foot or so without support, it can fly outward from centrifugal force. The piece will not only be bent, but it will present a very great danger to anyone standing near.
8. Other safety considerations: Hold one end of abrasive cloth strips in each hand when polishing rotating work. Don't let either hand get closer than a few inches from the work. Keep rags, brushes, and fingers away from rotation work, especially when knurling. Roughing cuts tend to quickly drag in and wrap up rags, clothing, neckties, emery clothes and hair. Move the carriage back out of the way and cover the tool with a cloth when checking boring work. When removing or installing chucks or heavy workpieces, use a board on the ways. To lift a heavy chuck or workpiece (larger than an 8-inch diameter chuck) get help or use a crane. Remove the tool or turn it out of the way during this operation. Do not shift gears or try to take measurements while the lathe is running and the workpiece is in motion. Never use a file without a handle as the file tang can quickly cut your hand or wrist if the file is struck by a spinning chuck jaw or lathe dog. Left-hand filing is considered safest in the lathe, that is, the left hand grips the handle while the right hand holds the tip end of the file.

INDEX

CHAPTER 1 GENERAL INSTRUCTION

| | |
|----------------------------------|-----|
| ◦ MACHINE SPECIFICATIONS | 02V |
| ◦ GENERAL LAYOUT OF LATHE | 03V |
| ◦ FOUNDATION PLAN | 04V |
| ◦ LIFTING THE MACHINE WITH CRANE | 05V |
| ◦ INSTALLATION OF MACHINE | 06V |
| ◦ CLEANING THE MACHINE | 06V |
| ◦ ELECTRICAL SUPPLY CONNECTION | 07V |
| ◦ LAYOUT OF ELECTRICAL BOX | 08V |
| ◦ ELECTRICAL COMPONENT LIST | 08V |
| ◦ ELECTRICAL CIRCUIT DIAGRAM | 09V |
| ◦ LUBRICATION CHECKS | 10V |
| ◦ CHUCK AND CHUCK MOUNTING | 11 |

CHAPTER 2 OPERATION

| | |
|---|---------|
| ◦ LATHE CONTROLS/ELECTRICAL CONTROL PANEL | 12V |
| ◦ HEADSTOCK SELECTORS | 13V |
| ◦ GEARBOX SELECTORS | 14V |
| ◦ APRON CONTROLS | 15 |
| ◦ THREADING DIAL INDICATOR | 16V |
| ◦ CROSS SLIDE | 17 |
| ◦ TOP SLIDE | 18 |
| ◦ TAILSTOCK | 19 |
| ◦ END GEAR TRAIN/DRIVING BELTS | 20V |
| ◦ LEADSCREW SHEAR PIN | 21 |
| ◦ FEED ROD FRICTION CLUTCH | 22 |
| ◦ LIMIT SWITCHES | 23 |
| ◦ LATHE ALIGNMENT | 24 |
| ◦ GAP BLOCK | 25 |
| ◦ TAPER ATTACHMENT | 26/27 |
| ◦ 5C COLLET CLOSER ATTACHMENT | 28V/29V |
| ◦ BED STOP | 30 |

CHAPTER 3 TO ACHIEVE MAXIMUM TURNING EFFICIENCY

| | |
|---|-----------|
| ◦ THE CUTTING SPEEDS AND FEEDS FOR HIGH SPEED STEEL CUTTING TOOLS | C301 |
| ◦ MATERIAL AND SHAPE OF CUTTING TOOLS | C302/C303 |
| ◦ APPLICATION OF COOLLANT FLUID | C304 |

CHAPTER 4 TROUBLE SHOOTING

| | |
|--------------------|------|
| ◦ TROUBLE SHOOTING | C401 |
|--------------------|------|

CHAPTER 5 SPARE PARTS (ILLUSTRATED)

CHAPTER 1 MACHINE SPECIFICATIONS

| MODEL | | ERL-1330V | ERL-1340V |
|--------------------------------|---------------------------------------|--|---|
| Capacity | Height of centers | 171mm (6.73") | |
| | Swing over bed | ø340mm (13.38") | |
| | Swing in gap | ø512mm (20") | |
| | Swing over cross slide | ø210mm (8.26") | |
| | Distance between centers | 760mm (30") | 1000mm (40") |
| | Width of bed | 230mm (9") | |
| | Gap width in front of faceplate | 150mm (5") | |
| Headstock & Main spindle | Spindle nose , Internal taper | D1-4 , MT. No.5 | |
| | Spindle center sleeve | MT. No.5 x MT. No.3 | |
| | Spindle bore | ø40mm (1.57") | |
| | Gear steps Spindle speed : / Range | $2 \text{ steps } \frac{L}{4P} = \frac{100 \sim 500 \text{ R.P.M.}}{500 \sim 3000 \text{ R.P.M.}}$ Infinitely variable | |
| Carriage | Length on bed / Width of carriage | 400mm (15.748") / 384mm (15.118") | |
| | Cross slide travel | 180mm (7") | |
| | Top slide travel | 100mm (4") | |
| Threads & Feeds | Whitworth threads : Kinds / Range | 45 Kinds / 2 ~ 72 T.P.I. | |
| | Metric threads : Kinds / Range | 39 Kinds / 0.2 ~ 14 mm | |
| | D.P. threads : Kinds / Range | 21 Kinds / 8 ~ 44 D.P. | |
| | M.P. threads : Kinds / Range | 18 Kinds / 0.3 ~ 3.5 M.P. | |
| | Longitudinal feeds | 0.05 ~ 1.7 mm (0.002" ~ 0.067") | |
| | Cross feeds | 0.025 ~ 0.85 mm (0.001" ~ 0.034") | |
| Tailstock | Quill diameter | ø50mm (1.968") | |
| | Quill travel | 112mm (4.5") | |
| | Taper of center | MT. No.3 | |
| Motor | Main spindle | AC 2.2kW (3HP), Inverter | |
| | Coolant pump | 1/8 HP | |
| Measurement | Weight (Net/Gross) Approx. | 850kgs / 1000kgs | 1000kgs / 1200kgs |
| | Packing sizes | Length | 2270mm (89.4") |
| | | Width x Height | Width 965mm (38") X Height 1745mm (68.7") |

**** Specification subject to change without notice ****

• STANDARD ACCESSORIES :


1. Backplate for 7" chuck
2. Dead center MT.3 made of carbon steel
3. Dead center MT.3 with carbide tip
4. Spindle center sleeve MT.5 x MT.3
5. Level pads ----- 6pcs
6. Toolset & Box
7. Operation manual & parts list

• OPTIONAL ACCESSORIES :


1. 3-Jaws scroll 7" chuck
2. 4-Jaws independent 8" chuck
3. 5C collet closer attachment
4. 5C collets (metric or inch)
5. Driving plate with Dog
6. Chuck safety guard
7. Hydraulic copying attachment
8. Tool post grinder attachment
9. Taper turning attachment
10. Electrical system for CE
11. Protect cover on leadscrew for CE
12. Steady rest w/ ball bearing
13. Follow rest w/bronze tip
14. Faceplate 10"
15. Drill chuck & arbor
16. Rotating center MT.3
17. Halogen lamp
18. Quick change tool post
19. Carriage micro stop set
20. Digital read out system
21. Full length splash guard

CHAPTER 1 • GENERAL LAYOUT OF LATHE

1. Headstock
2. Chuck guard (optional)
3. Spindle
4. Bed
5. 4-Way tool post
6. Top slide
7. Saddle and Cross slide
8. Splash guard (optional)
9. Tailstock
10. Tail-end Plinth
11. Leadscrew
12. Feed shaft
13. Apron
14. Front moveable chip tray
15. Footbrake
16. Carriage micro stop set (optional)
17. Head-end Plinth
18. Gearbox
19. End Cover (Gear Train)



CHAPTER 1 ◦ FOUNDATION PLAN




| Model | LCY | FB | BC | BT | FW |
|-------------|--------|---------|---------|---------|--------|
| ERL – 1330V | 2360mm | 1118 mm | 1072 mm | 1352 mm | 1750mm |
| ERL – 1340V | 2660mm | 1418 mm | 1072 mm | 1352 mm | 2050mm |

CHAPTER 1 ◦ LIFTING THE MACHINE WITH CRANE

* PREPARATION

- Machine weight model ERL-1330V about 980kgs.
ERL-1340V about 1150kgs.
- Make sure that the minimum crane capacity is more than 2 tons for security.
- Only an authorized crane operator should use the lift machine.
- Crane work should be cooperatively done by two persons, that is, an operator and a watchman. not to damage projecting on the machine perimeter.
- To put in the jig with wire set inserting to bed way
- Make sure that two hexagon nuts is fixed.
- keep the machine's center of gravity at the center of the crane.



CHAPTER 1 • INSTALLATION OF MACHINE


* Notice items:

1. Locate the machine on a solid foundation according to foundation plan as shown in page 4V.
2. There must be sufficient power capacity.
3. The machine must not be adjacent to direct sunlight.
4. Don't pile up things on the floor around the machine and must keep floor dry.
5. Must reserve enough space for opening the door of electric box for maintenance and accessing for operation.
6. Position lathe on foundation and adjust each of the six mounting plinth to take equal share of the load.
7. Using an engineers' precision level on the bedways, adjust the plinth to level up machine.
8. Periodically, check bed level to ensure continued lathe accuracy.

• CLEANING THE MACHINE

* Notice items:

1. Before operating any controls, remove the anti-rust coating on all slideways and other places.
2. When cleaning, Use spirit or kerosene, instead of cellulose solvents, which may damage the paint finish.
3. Oil all brightly machined surfaces immediately after cleaning. apply machine oil on slideway and heavy oil or grease on the end gears.
4. It is recommended that all slideways, the leadscrew and feed shaft are cleaned (a bristle paint brush is useful for this) and lightly.



CAUTION:

DO NOT USE AIR COMPRESSOR TO CLEANING.


CHAPTER 1 ◦ ELECTRICAL SUPPLY CONNECTION

* ELECTRIC BOX INSTRUCTION

- This lathe is wired according to importer's required electric specification. If it happens that the wiring specification need to be rectified, Please refer to wiring diagram shown in this instruction manual.(page 07V,08V, 09 V)
- For electrical connection, simply connect R, S, T, of your supply lines to R, S, T, of connect terminals on left bottom of electrical compartment.
- Main motor rotation must be clockwise viewed from the pulley end. If motor runs in wrong direction, turn OFF the main power and exchange R and T off the three phase lines.




CHAPTER 1 ◦ LAYOUT OF ELECTRICAL BOX



◦ ELECTRICAL COMPONENT LIST

| MODEL | DESCRIPTION | SPECIFICATION | Q'TY | SYMBOL |
|--------------------------------|---------------------------|-----------------------------|------|-------------|
| AC 2.2kW 3HP 4P Inverter | —1330V AC Magnetic switch | TENLC1D096B7 | 1 | K1 |
| | —1340V Over relay | TENLR3D046 | 1 | F4 |
| | Main fuse base | TFU-303 3P50A | 1 | F1 |
| | Fuse base | TFB-102 2P10A | 1 | F2 , F3 |
| | Terminal board | TBR-20(TEND) | 7 | T.B |
| | Terminal board | TBR-10(TEND) | 24 | T.B |
| | Micro switch | TM-1307(TEND) | 1 | LS1 |
| | Micro switch | TM-1704M(TEND) | 1 | LS2 |
| | Micro switch | TM-1308(TEND) | 2 | LS3 , LS4 |
| | E-Stop | ALEPB-22-1B | 1 | E-STOP |
| | Spindle motor jog | APB-22-1A-G | 1 | PB1 |
| | Pump run | ASS-22-2P-1A-G | 1 | SW1 |
| | Power lamp | ALPL-22-30V-W | 1 | POWER LAMP |
| | Relay | MY4NJ AC24V | 3 | KR1,KR2,KR3 |
| | Relay | MY2NJ AC24V | 1 | KR4 |
| | R.P.M Meter | PF-L@ A0603084G1286 | 1 | R.P.M |
| | Proximity switch | FQP2-1604-A3U2 10~30VDC NPN | 1 | R.P.M |
| | Inverter relay pcb | SC-001 | 1 | PCB |
| | Transformer | 140VA | 1 | T1 |
| | Fan | FAN 4" AC220V | 1 | FAN |
| | 5HP Inverter | YASKAWA CIMR-G7A23P7 | 1 | INVERTER |
| | Brake resistance | 600W 40 Ω | 1 | R |

CHAPTER 1 • ELECTRICAL CIRCUIT DIAGRAM



CHAPTER 1 • LUBRICATION CHECKS

* HEADSTOCK / GEARBOX / CARRIAGE, APRON / TAILSTOCK

Before operating the machine, make the following important checks:

1. The headstock is filled to level marked on oil sight window with Shell Tellus oil 32 or equivalent. Check oil weekly and change the oil every 6 month.
2. The gearbox is filled to level marked on oil sight window with Shell Tellus oil 68 or equivalent. Check oil weekly and change the oil every year.
3. The carriage apron is filled to level marked on oil sight with Shell Tellus oil 68 or equivalent. Check oil weekly and change the oil every year.

There are two oil ball on the tailstock & a oil cap on the bracket.

4. Please add No.68 oil 3 c.c. to them respectively every day before operating to ensure the smoothness of ways.


There are three oil ball on the cross slide & top slide.

5. Please add No.68 oil 10 c.c. to them respectively every day before operating to ensure the smoothness of leadscrews.

A manually operated one shoot lubrication pump is incorporated into the apron. Drawing oil from the apron reservoir.

It enables the operator to ensure that the slideways are kept adequately lubricated.

The pump should be operated before and occesionaly during the work period.



The apron can be unscrewed by 6 mm allen wrench the drain plug in the bottom plate.

CHAPTER 1 ◦CHUCK AND CHUCK MOUNTING(for D1-4 spindle)

* WARNING: USE ONLY HIGH-SPEED CHUCKS WITH THESE MACHINES.


- When fitting chucks or faceplates, ensure that spindle and chuck tapers are scrupulously clean that all cams lock in the correct positions the first.
 - It may be necessary to re-set the camlock studs(A) when mounting a new chuck. To do this, remove the hexagon socket locking screws(B) and set each stud so that the scribed ring(C) is flush with the rear face of the chuck—with the slot—lining up with the locking screw hold.
 - Now mount the chuck or faceplate on the spindle nose and tighten the six cams in turn.
 - When fully tightened, the cam lock line on each cam should be between the two V marks on the spindle nose.
If any of the cams do not tighten fully within these limit marks, remove the chuck or faceplate and re-adjust the stud as indicated in the illustration.
 - Fit and tighten the locking screw(B) at each stud before remounting the chuck for work. A reference mark should be made on each correctly fitted chuck or faceplate to coincide with the reference scribed on the spindle nose. This will assist subsequent remounting.
- DO NOT INTERCHANGE CHUCKS OR FACE PLATES BETWEEN LATHES WITHOUT CHECKING FOR CORRECT CAM LOCKING.

IMPORTANT:

Take careful note of speed limitations when using faceplates;
10 inch faceplates should not be run at speeds higher than 1305 rev/min.
and 12 inch faceplates at not higher more than 990 rev/min.

Reference mark on spindle nose and chuck

Turn stud out one turn



CHAPTER 2 • LATHE CONTROLS




- A. Electrical control panel.
- B. Headstock selector for L/H 2-section speed.
- C. Gearbox (threads and feeds)
- D. Apron control units, for surfacing, sliding and threading controls.
- E. Switch handle, for spindle rotation, forward, stop and reverse.
- F. Footbrake.

• ELECTRICAL CONTROL PANEL

Except the lathe isolator, all electrical controls are installed on top of headstock.

- 1. Coolant pump ON / OFF switch.
- 2. Power ON light. it will glow when the electricity is ON.
- 3. The emergency stop, serving as electricity ON / OFF switch also.
- 4. Inching : Push it to move spindle slightly for checking workpiece is clamped tightly and coaxial in the chuck before cutting!
- 5. Speed adjusting knob.
- 6. Speed indicator.



CHAPTER 2 • HEADSTOCK SELECTORS

* (H1) Spindle speed selectors

1. The middle upper selectors on headstock are for spindle speed selection. There are 2 spindle speeds, as shown on speed chart, divided into 2-section speed.
2. L 100~500 R.P.M.
H 500~3000 R.P.M.
Infinitely variable

* (H2) H-N-L selector for gearbox

1. Following each feed rate or thread pitch on gearbox thread and feed chart, there is a prefix of either H or L, move
2. H-N-L selector to H or L accordingly for feeding or threading. If this lever is positioned at N, the headstock rotation will not be transmitted to gearbox.

*WARNING:

HIGH POSITION DO NOT EXCEED SPINDLE SPEED OF 330 R.P.M.

* (H3) Apron orientation selector

1. This selector may affect the rotation orientation of leadscrew, feed rod and henceforth the movement direction of apron.
2. FORWARD(left-hand arrow) is used for cutting right-hand threads. REVERSE(right-hand arrow) is used for cutting left-hand threads.

* HEADSTOCK SELECTORS

- (H1) H or L two section speed (H3) Apron orientation selector
(H2) Low-N-High selector for gearbox

CORRECT SPEED CHANGE PROCEDURE




CAUTION:

DO NOT USE RICHING FUNCTION WITH SPEED CHANGE. BECAUSE IT COULD DAMAGE THE GEARS AND CAUSE INTERMITTENT NOISE DURING SPINDLE RUNNING LATER ON.

SPEED CHANGE PROCEDURE :

1. Stop the spindle.
2. Insert a chuck wrench into the chuck square slot and hold it with right hand.
3. Use left hand to hold the headstock selector (as indicated in drawing above).
4. Use right hand to shake the chuck and try to shift selector position with left hand at the same time.
5. Always shift selector into neutral position before speed change.
6. Use right hand to shake chuck again while use your left hand to shift selector to engage into desired speed zone slowly.



CHAPTER 2 ◦ GEARBOX SELECTORS

* Gearbox, thread and feed selectors

- All the thread pitches and feeds directly available from the gearbox are shown on the data plate fitted on the front of headstock and the positioning control levers are (G1), (G2), (G3), and (G4).

* End gear trains diagram

- The end-gear train should be arranged as in the diagram shown on the dataplate (G5) to meet threading requirements.

* FEEDS:

- Sliding feeds per spindle revolution range from 0.002 to 0.067 inch.
(0.05 to 1.7mm)
- Surfacing feeds per spindle revolution range from 0.001 to 0.034 inch.
(0.025 to 0.85mm)

| | | |
|-----------------------|-----------------------------------|-------------------------------------|
| Threads & Feeds | Whitworth threads : Kinds / Range | 45 Kinds / 2 ~ 72 T.P.I. |
| | Metric threads : | 39 Kinds / 0.2 ~ 14 mm |
| | Diametral pitch (D.P.) worm gear | 21 Kinds / 8 ~ 44 D.P. |
| | Module pitch (M.P.) worm gear | 18 Kinds / 0.3 ~ 3.5 M.P. |
| | Longitudinal feeds | 0.05 ~ 1.7 mm (0.002" ~ 0.067") |
| | Cross feeds | 0.025 ~ 0.85 mm (0.001" ~ 0.034") |


* GEARBOX SELECTORS

- (G1) A,B,C three section selector
- (G2) R,S,T three section selector
- (G3) 1~8 eight section selector
- (G4) V~Z five section selector
- (G5) End gear train diagram



CHAPTER 2 • APRON CONTROLS

- * For surfacing, sliding and thread cutting controls.
In addition to handwheel traverse the carriage can be power-operated through controls on the front of the apron.



(A1). Surfacing and sliding selection lever:

When it is in and is moved downward, surfacing is in operation;
When it is pulled out and moved upward, sliding is in operation.

(A2). Direction selection push button:

Either move this push button inward or outward to change direction of carriage movement or cross-slide. With this push button the operator can ignore the direction of spindle or leadscrew.

(A3). Half-nut lever:

When it is pressed downward, the half-nut will be engage with leadscrew for thread cutting. To avoid undue wear, release the nut when not thread cutting. An interlock within the apron prevents inadvertent engagement of this lever when in feeding operation.

(A4). Carriage handwheel.

(A5). Cross slide handwheel.

(A6). Compound rest handwheel.

(A7). Threading dial indicator.

(A8). Spindle Rotation, Forward, Stop and Reverse:

The forward and reverse rotation of spindle is operated by starting lever at right side of apron and controlled by limit switches right-side the bedway.

CHAPTER 2 • THREADING DIAL INDICATOR

* For threads cutting

- Tighten the handnut to retain indicator in engagement when engaging the indicator with the leadscrew. When not required, release hand-nut and swing indicator out engagement.
- To cut threads of even number per inch, the leadscrew nut can be closed as any line on the dial passes the datum mark.
- To cut threads of odd numbers per inch, close the leadscrew nut at any NUMBERED line.
- Fractional threads of $1/2$ or $1/4$ T.P.I. may be cut by closing the nut at the SAME NUMBERED LINE on each pass of the tool.
- This dial can not be used with an IMPERIAL leadscrew to cut metric threads, D.P., M.P. which are shown on gear box data plate. For the threads being shown, the leadscrew nut must be kept closed. Use apron control lever after each thread cutting when the tool is withdrawn to original start of thread cutting operation.




* Multi-start threads can be cut on a lathe in three ways:

1. By repositioning the compound (top) slide one pitch forward for each start. Note that the slide is normally set at 90 deg. to the axis of the machine cross-slide. The accuracy of this method depends upon the skill of the operator.
 2. By using an accurately divided driver plate and turning the work-piece one division forward for each start.
 3. By advancing the driver gear a calculated number of turns to advance the spindle by one pitch of the thread to be cut. The accuracy of this method is that of the machine.
- With ALL SERIES lathes, two ratios exist between the spindle and driver gear shift, i.e. the LOW range where the ratio is 1:2 and the HIGH range where the ratio is 2:1.
 - In order to use this method, the number of teeth on the driver gear must be divisible by the number of starts being cut. The driver gear is then advanced by half this number of teeth when in LOW range, and conversely, by twice the number of teeth when in HIGH range.
 - The limitation of this method depends upon whether the number of teeth on the driver gear without a remainder.
 - On the standard end gear train for this machine the driver gear has 24 teeth; so that two, three or four start threads, can readily be cut. For other odd numbers of start a choice must be made of methods 1 or 2.

CHAPTER 2 • CROSS SLIDE

* Cross-slide nut adjusting.

- Reduce backlash by slackening rear hexagon socket head bolt (M6) in top of cross slide, then carefully screw in the center set screw (S6) to adjust a wedge within the split nut.
- Mark only small adjustment at time and retighten two bolts (M6) before operating the cross slide several times by hand to be sure of smooth operation throughout full travel.





* Saddle & Cross slide gibs adjusting.

- Tapered gib strip are fitted to slideways of saddle cross-slide and top (compound) slides so that any slackness which may develop can be diminished. Check and adjust them every six months.
- Ensure that slideways are thoroughly cleaned and lubricated before attempting adjustment. According to the following steps :
 1. Use flat head screw driver to loosen the adjust screw (F1) & (R4), / (R6) about 1/2 circle CCW.
 2. Appropriately tighten adjust screw (F2) & (R3) / (F5) about 1/2 circle CW.
 3. Move saddle leftward and rightward to satisfied smoothness.
 4. Move cross slide forward and backward to satisfied smoothness.

CHAPTER 2 • TOP SLIDE

* Top slide indexing

- A solid top slide is fitted as standard equipment to the cross-slide mounted on a swivel base which is marked 0-45-0-45 degree for normal indexing.



* Top slide gibs adjusting.

You should regularly check and adjust them every six months.



Ensure that slideways are thoroughly cleaned and lubricated before attempting adjustment. According to the following steps :

1. Use flat head screw driver to loosen the adjust screw(P1) , about 1/2 circle CCW.
2. Appropriately tighten adjust screw(P2), about 1/2 circle CW.
3. Move top slide leftward and rightward to a satisfied smoothness.


CHAPTER 2 • TAILSTOCK

* Quill lubricate

- There are two oil ball on the tailstock.
- Please add No.68 oil 3 c.c. to them respectively every day before operating to ensure the smoothness of ways.



Detail of mark D



* Operation

1. The tailstock can be freed for movement along the bed by unlocking clamping lever(A).
2. Release this clamping lever(A) before attempting to move the tailstock after and on completing of the need, lock it again for extra clamping.
3. The tailstock quill can be locked by clamp lever(C).


* Adjustment / re-alignment

1. The tailstock also can be set over for turning shallow tapers or for re-alignment.
2. Release the clamping lever(A) and adjust screw(S) at each side of the base to move tailstock laterally across the base.
3. An indication of the set-over is given by the datum mark(D) at the tailstock end face.
4. Tight clamp lever after adjusting set-over.

CHAPTER 2 • END GEAR TRAIN

* Notice items:


1. Drive from headstock to gear box is transmitted through a enclosed by the headstock end cover. Intermediate gears are carried on an adjustable swing-frame(M).
2. Gears must be thoroughly cleaned before fitting and backlash must be maintained at 0.005"(0.127mm) for correct meshing.
3. Lubricate gear regularly with heavy oil or grease.



• DRIVEING BELTS

* Notice items:

1. To adjusting belt tension, remove the cover plate on back of the headstock and adjust the hexagon nuts(X) on the hinged motor platform.
2. Ensure that the motor is correctly aligned with the lathe axis.
3. Apply light finger pressure at a point midway between motor and head-stock pulleys, the resulted depression compare to other belt will be about 3/4" (19mm) when under tension.



CHAPTER 2 ◦ LEADSCREW SHEAR PIN

* Safety feature

1. The transmission is protected against severe overload by a shear pin fitted into the leadscrew drive, just beside the right hand of the gearbox.
2. To replace a shear pin:
 - First disengage drive to the leadscrew (63005-*0) by setting the right-hand lever of the gearbox to the position W or X.
 - Move the shroud washer (63008) with snap ring rightward to the spring cover (63006).
 - Then rotate the leadscrew by hand carrying the broken pin to the frontview, on same level to the slot of flanged bearing (30017).
 - By a magnetism screw driver can easily remove the broken pin head from the collar (63009), and other broken pin from gear box housing slot hole.
 - Align the holes in flanged-shaft (30014), collar (63009) and shroud washer (63008) then insert a new pin (63010) and turn the shroud washer half circle to leftward to the collar (63009) with snap ring for retain the new shear pin.



Part name : Shear pin

Drawing no. : 63010


Material : S45C (SAE 1045)

Scale : 5/1

Unit : mm



BEFORE REPAIR



REPAIR PROCESS

FINISHED

CHAPTER 2 • FEED ROD FRICTION CLUTCH

* Safety feature

1. The friction clutch at left side of feed rod serves as safety device against overload.
2. In case of overload in feeding, the friction clutch will disengage feed rod from transmission and hence the lathe runs freely without any damage.
3. The friction clutch is adjustable to take different cutting loads depending on actual requirement.
4. To increase/decrease cutting load, P/N 63016 clutch collar should be turned reverse/forward. After adjustment, it should be tightened the set screw (S6) into slot again.

IMPORTANT:

WHEN ADJUSTING OVERLOAD FEED CLUTCH FOR SUITABLE FRICTION TO WORKING, MUST BE CHECKING THE CARRIAGE AUTO-FEEDING TOWARD HEADSTOCK, WHEN THE APRON SAFETY PLATE(40078) TOUCHING TO STOPPER(63012) IN THIS MOMENT THE CARRIAGE WILL BE STOP, THIS IS MANUFACTURE NORMALLY TESTING.



Stopper(63012)

Is designed to stop the carriage at given set-up

CHAPTER 2 • LIMIT SWITCHES

* Foot brake:

1. One limit switch and two limit switches to servo for instant foot brake and spindle forward–reverse rotation respectively.
2. Make sure always the smooth contact of small wheel of limit switch with the cam at end of foot brake and starting lever respectively.

Spindle control lever



Foot brake limit switch

Forward/reverse limit switches



* Safety interlock:

1. IF the end cover is not closed, then the spindle and coolant pump can not rotate and start.
2. IF the chuck guard (optional accessory) is not swivel down, then the spindle and coolant pump can not rotate and start.

Chuck guard



Chuck guard limit switch

End cover limit switch




CHAPTER 2 • LATHE ALIGNMENT

* Lathe alignment :

- With the lathe installed & running we recommend verification on machine alignment before commencing work.
- Check levelling & machine alignment at regular periods to ensure continued lathe accuracy.



(I) 2-Fixing screws
(K) 2-Adjusting screws



(J) 2-Hex. socket head bolts

* Headstock check :

1. Take a light cut with a cutting tool over a 6" (152mm) length of 2" dia (Ø50mm) steel bar gripped in the chuck but not supported at the free end.
2. Micrometer readings at each end of the turned length (at A & B reference Fig. 24-P1) should be the same.
3. To correct a difference in readings, slacken the four headstock hold-down screws(I) behind headstock and (J) under the headstock, then adjust the set-over adjusting screws(K).
4. After adjustment, tighten screw(I) / (J) first then screw(K).
5. Repeat the test-cut / micrometer-reading sequence until micrometer reading are identical, i.e.




Fig. 24-P1





Fig. 24-P2

* Tailstock check : (reference Fig. 24-P2)

1. Using a 12" (305mm) ground steel bar fitted between headstock and tailstock centers, check the alignment by fitting a dial-test indicator to the toolpost and traversing the center line of the bar.
2. To correct error, release the tailstock clamp lever and adjust the set-over screws provided.
3. Continue with checking and correction until alignment is perfect.

CHAPTER 2 ◦ Gap Block(For Gap Bed Type Lathe)


- When removing the gap block from bedway , be very careful in loosening the five fixing bolts and lift the gap until guiding taper pins seperate from bedway completely.
- When loosening the fixing bolts and seperating the taper pin , every particular precaution should be paid to prevent any small damage to fixing bolts and taper pins.
- The taper pins should be left in the gap portion after removal of the gap block.
- Removed gap block mut be stored in a very clean and safe place with every precaution against damage and rust.
- The taper pins should be greased so as to make it easy to reset the gap block with optimum original accuracy.
- Be careful not to have dirt or chips entering into taper pin hokes , holes for fixing bolts or on the surface where gap block is to be reset.
- Keep them always very clean.



CHAPTER 2 ◦ TAPER ATTACHMENT

- 1) Release P/N M10 nut, P/N 50026 cap collar, P/N NTB/AS2 1226 thrust bearing, then slide P/N 50018 bracket out of saddle (shown on Page F02).
- 2) Release P/N M6 screws and take off P/N 80002 plate on taper attachment.(Shown on page M02).
- 3) Mount P/N 80005 yoke plate on cross slide shaft (P/N 50016 screw) and re-mount P/N M10 nut, P/N 50026 cap collar, P/N NTB/AS2 1226 thrust bearing as shown on diagram on page F02/M02.
- 4) Screw in 2 P/N M6X20 Hex. screws head bolt to connect P/N 80005 yoke plate and P/N 80004 yoke.
- 5) Align taper attachment to the slide ways of P/N 80005 yoke plate and P/N 80004 yoke , and meet the four holes on mounting face of attachment with those four on back of carriage, screw them tightly.
- 6) Mount the bracket plate on back bedway, adjust the length of connecting rod according to work condition, then screw tightly.
- 7) Set P/N 80009 swive slide guide to the required angle and then the nuts P/N M8x30 Hex. socket head bolt are tightened. Hence the guide is clamped securely.
- 8) Try a few test cuts on test workpiece until the operation is smooth and taper angle is correct.
- 9) The completed installation is as shown on Page 27/M01/M02

CHAPTER 2 ◦ TAPER ATTACHMENT





CHAPTER 2 ◦ 5C COLLET CLOSER ATTACHMET

If 5C collet closer attachment is not mounted on lathe when delivered, it is supplied in three seperated assembly; bush, handle rod and main assembly. When mountingthe the attachment, it is better to proceed as follows: (See page 29V/L01V/L02V)


- 1) Clear the taper hole of spindle nose and P/N 90026 bush very thoroughly. Then put the bush inside the taper hole of spindle nose. The pin (P/N 90027) inside the bush should be at top side.
- 2) Locate the position of P/N 90048 bracket and P/N M5x15 Hex. socket head bolt out of the small hole of end gurard. Then drill and tap the three holes for P/N M6x25 Hex. socket head bolt
NOTE: The three hole for P/N M6x25 Hex. socket head bolt should not be drilled through.
- 3) Mount the main assembly by putting P/N 90028 tube though inside headstock spindle, screw in P/N 90023 hub to threaded tail end of spindle.
- 4) Screw in P/N M6x25 Hex. socket head bolt to the three hole so as to secure P/N 90048 bracket firmly onto headstock.
- 5) Screw in P/N 90045 handle rod to P/N 90044 handle casting.
- 6) Put a 5C collet into P/N 90026 bush. The pin (P/N 90027) should be inside the slot of 5C collet. And turn the tail end into the internally threaded end of P/N 90028 tube.
- 7) Operate P/N 90046 handle to test whether the chucking operation of collet is smooth and forceful or not. If not, loosen P/N 90035 knob and turn P/N 90043 collar inward or outward until the chucking operation of collet is smooth and forceful, then tighten, P/N 90035 knob again.
- 8) Seperate P/N 90047 connector casting from P/N 90050 screw and remove P/N 90028 tube out of headstock spindle.
- 9) Mount end guard into position.
NOTE : P/N 90050 screw should project out of the small hole of end guard.
- 10) Place P/N 90028 tube inside headstock from outside of end cover and proceed as aforesid steps, then connect the P/N 90050 screw to P/N 90047 connector casting again.
- 11) The whole set of 5C collet closer attachment is now ready for operation.

CHAPTER 2 • 5C COLLET CLOSER ATTACHMET



CHAPTER 2 • BED STOP

- NOTE : Refer to page N01/N02, the diagram of bedstop , when P/N 70048-13 body is mounted onto bedway and P/N 18-70059 clamp plate is screwed to P/N 70048-13 body , there is always about 2mm clearance between bottom body and clamp plate. The clearance is to be made up by screwing up two set screws(P/N M10x20 set screw). In this way , the beedstop will be mounted very firmly onto bedway.
(The same way suit for that micrometer bed stop ref to page 001/002)



Bedstop

CHAPTER 3 • TO ACHIEVE MAXIMUM TURNING EFFICIENCY

In order to make the most economical use of the lathe and to achieve maximum turning efficiency in surface finish and shortest machining time, the cutting conditions of set-up of cutting tool, cutting speed, feed, depth, and application of coolant fluid should be established. In determining the cutting speed, feed and cutting depth, the material and diameter of workpiece and material and shape of cutting tool are the most important factors. In determining the most efficient speed for various kind of material, the operator is advised to refer to machining handbook.

(1) The Cutting Speeds and Feeds for High Speed Steel Cutting Tools are as Follows:

| | Low Carbon Steel | High Carbon Steel Annealed | Alloy Steel Normalized | Aluminum Alloys | Cast Iron | Bronze |
|------------------------|------------------------|-------------------------------------|------------------------------|--------------------|---------------|---------------|
| Roughing speed SFM | 90 | 50 | 45 | 200 | 70 | 100 |
| Finishing speed SFM | 120 | 65 | 60 | 300 | 80 | 130 |
| Feed IPR roughing | .010– .020 | .010– .020 | .010– .020 | .015– .030 | .010– .020 | .010– .020 |
| Feed IPR finishing | .003– .005 | .003– .005 | .003– .005 | .005– .010 | .003– .010 | .003– .010 |

Spindle speeds are determined by using—following formula, which is used in turning between centers as well as in facing

$$\text{RPM} = \frac{\text{CS} \times 4}{D}$$

RPM=Spindle speed, revolution per minute
D=Diameter of workpiece
CS=Cutting speed in surface feet per minute(SFM)

EXAMPLE

If the cutting speed is 40 for a certain alloy steel and the workpiece is 2 inches in diameter, find the rpm as follows:

$$\text{RPM} = \frac{40 \times 4}{2} = 80$$

After calculating the PRM, use the nearest or next lower speed on the lathe and set the spindle speed.

CHAPTER 3 • MATERIAL AND SHAPE OF CUTTING TOOLS

(2) Material And Shape of Cutting Tools

the most commonly used material for turning tools is high speed steel, the recommended shape (cutter angle degrees) for high speed steel tools is as follows:

| | End Relief | Side Relief | Side Rake | Back Rake |
|----------------------|------------|-------------|-----------|-----------|
| Aluminum | 8 to 10 | 12 to 14 | 14 to 16 | 30 to 35 |
| Brass, free cutting | 8 to 10 | 8 to 10 | 1 to 3 | 0 |
| Bronze, free cutting | 8 to 10 | 8 to 10 | 2 to 4 | 0 |
| Cast iron, gray | 6 to 8 | 8 to 10 | 10 to 12 | 3 to 5 |
| Copper | 12 to 14 | 13 to 14 | 18 to 20 | 14 to 16 |
| Nickel and monel | 12 to 14 | 14 to 16 | 12 to 14 | 8 to 10 |
| Steels, low carbon | 8 to 10 | 8 to 10 | 10 to 12 | 10 to 12 |
| Steels, alloy | 7 to 9 | 7 to 9 | 8 to 10 | 6 to 8 |

However, the cutting tool materials such as carbon steels and high speed steel that served the needs of machining in the past years are not suitable in many application today. Tougher and harder tools are required to machine the tough, hard space age metals and new alloys. The knowledge of carbide cutting tools and ability to select them for specific machining tasks will affect productivity directly.

The following steps may be used in selecting the correct carbide tool for a job.

- Step 1. Establishing the cutting conditions of speed, feed, and depth of cut to establish metal removal rate.
- Step 2. Selecting cemented carbide grade. Its grade classification and comparison table with CCPA "C" numbers and manufacturers designations are briefed as follows:

CHAPTER 3 • MATERIAL AND SHAPE OF CUTTING TOOLS

The Grades Listed Are Those Usually Recommended
by the Manufacturer for the Categories Shown

| APPLICATION | | | Carmet | Ex-cell-o | Firth Sterling | Greenleaf | Kennametal | Metal Carbides | Sandvik | Valenite |
|---|---------------------|------|----------------|-------------------|-------------------|------------|-------------|-------------------|------------|----------------|
| Cast irons | Roughing cuts | C-1 | CA3 | E8 | H HB | G10 | K1 | C89 | H20 | VC-1 |
| Nonferrous, Nonmetallic, Hi-Temperature alloys | General purpose | C-2 | CA4 CA443 | E6 XL620 | HA HTA | G20 G25 | K6 K68 | C91 | H20 | VC-2 VC-28 |
| 200&300 series stainless | Light finishing | C-3 | CA7 | E5 | HE HTA | G30 | K8 K68 | C93 | R1P | VC-3 |
| | Precision boring | C-4 | CA8 | E3 | HF | G40 | K11 | C95 | H1P H05 | VC-4 |
| | Roughing cuts | C-5 | CA721 CA740 | 10A 945 | NTA TXH | G50 G55 | K42 K21 | S-880 | S-6 | V-55 VC-125 |
| Carbon steels | General purpose | C-6 | CA720 | BA 606 | T22 T25 | G60 | K2S K21 | S-900 S-901 | S-4 | VC-6 |
| Alloy steels | Finishing cuts | C-7 | CA711 | 6A XL70 6AX | T25 T31 | G70 G74 | K45 K5H | S-92 S-900 | SM | VC-7 VC-76 |
| 400 Series stainless | Precision boring | C-8 | CA704 | 6AX XL88 | T31 | G80 | K7H K165 | S-94 | F02 | XC-8 XC-83 |
| | Hi-velocity | C-80 | | | | | C06 | | | |

CHAPTER 3 • APPLICATION OF COOLANT FLUID

- Step 3. Select nose radius
- Step 4. Select insert shapes
- Step 5. Select insert size
- Step 6. Select insert thickness
- Step 7. Select tool style
- Step 8. Select rake angle
- Step 9. Select shank size

(3) APPLICATION OF COOLANT FLUID

Coolants are used for heavy duty and production turning. Oil–water emulsions and synthetic coolants are the most commonly used, while sulfurized oils usually are not used for turning operations except for threading. Most job work or single piece work is done dry. Many shop lathes do not have a coolant pump and tank, so, if any coolants and cutting oils for various materials are given in following table.

Coolants and Cutting Oils Used for Turning

| Material | Dry | Water Soluble Oil | Synthetic Coolants | Kerosene | Sulfurized Oil | Mineral Oil |
|------------|-----|-------------------|--------------------|----------|----------------|-------------|
| Aluminum | | x | x | x | | |
| Brass | x | x | x | | | |
| Bronze | x | x | x | | | x |
| Cast iron | x | | | | | |
| Steel | | | | | | |
| Low carbon | | x | x | | | |
| Alloy | | x | x | | x | |
| Stainless | | x | x | | x | |

CHAPTER 4 • TROUBLE SHOOTING

| | Trouble or Failure | Possible causes | Correction |
|----|--|--|---|
| 1 | The electricity is on, but the spindle does not run after the starting lever is moved downward or upward | 1) Fuse is burned 2) Thermal relay is overload | 1) Replace fuse 2) Reset thermal relay |
| 2 | Outflow of coolant fluid is weak | 1) Running orientation of coolant pump is wrong 2) The inside of coolant pipe is rusted or otherwise restricted | 1) interchange any two line of 3 phase line 2) Clear the pipe by compressed air or rigid steel rod |
| 3 | No coolant fluid comes out of coolant nozzle | The steel ball inside the coolant pipe is stuck to "O" ring | Separate the steel ball from "O" ring by compressed air |
| 4 | Spindle does not stop instantly even when treadle is fully depressed | The height of treadle is too low | Adjust brake belt to more tight |
| 5 | Intermittent noise in headstock | Headstock shift levers are not in position | Stop the machine and re-shift levers to the position where steel ball slips into the concave |
| 6 | Headstock and gear train are running and starting lever is moved upward or downward, but the feed rod or leadscrew does not rotate | Gearbox shift levers are not in position | Shift levers to correct positions as specified on data plate |
| 7 | When turning long workpiece the right end is smaller than the left end in diameter | Tailstock is not in good alignment to headstock | Offset tailstock until the center line between headstock is parallel to carriage movement |
| 8 | Chatter line occurs on turned workpiece | 1) Lathe cutter is dull 2) Spindle taper roller bearing is too loose | 1) Sharpen the cutting angles of lathe cutter 2) Adjust the tightness of P/N 10011 nut. |
| 9 | No Oil comes out of one shot lubrication | Too much air is caught oil groove | Keep on pushing one shot lubrication pump until all air is driven out |
| 10 | Sharp, shriek noise in braking action | Brake lining has been worn out | Replace the brake lining |
| 11 | Carriage vibrates during heavy cutting | P/N 50053/50056 gib is too loose in fitting | Adjust screw cross slide & tool slide to drive the gib slightly inside |
| 12 | Oil leaks at right side of gearbox | The lubricant in gearbox is too light | Replace with slightly denser lubricant in gearbox |


CHAPTER 5 SPARE PARTS (ILLUSTRATED)

- HEADSTOCK ASSEMBLY (E.V.S. MODEL).....A01V/A02V/A03V/A04V/A05V
PARTS LIST.....A06V/A07V
- GEARBOX ASSEMBLYB01/B02/B03
PARTS LIST.....B04/B05
- APRON(L.H) ASSEMBLYC01/C02
PARTS LIST.....C03/C04
- DIAL INDICATOR ASSEMBLY.....D01
METRIC (LEADSCREW PITCH 6).....D02
IMPERIAL (LEADSCREW 4 T.P.I.).....D03
PARTS LIST.....D04
- 4 WAY TOOL POSTE01/E02/E03
PARTS LIST.....E04
- SADDLES ASSEMBLYF01/F02/F03
PARTS LIST.....F04/F05
- BED & SHAFTS ASSEMBLYG01/G02
PARTS LIST.....G03
- END GEAR ASSEMBLYH01V
METRIC (LEADSCREW PITCH 6) FOR 1330/1340H02V
IMPERIAL (LEADSCREW 4 T.P.I.) FOR 1330/1340.....H03V
- MAIN MOTOR ASSEMBLY
(E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY).....I01V/I02V
PARTS LIST.....I03V
- CABINET AND PANEL
(E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY).....J01V/J02V
PARTS LIST.....J03V
- CONVENTIONAL TAILSTOCK ASSEMBLYK01/K02
PARTS LIST.....K03
- 5C COLLET CLOSER ATTACHMENT
(E.V.S. MODEL).....L01V/L02V
PARTS LIST.....L03V
- TAPER ATTACHMENTM01/M02
PARTS LIST.....M03

CHAPTER 5 SPARE PARTS (ILLUSTRATED)


- ◉ BED STOPN01/N02
PARTS LIST.....N03
- ◉ BED STOP
MICROMETER BEDSTOP.....001/002
PARTS LIST.....003
- ◉ STATIONERY STEADYP01/P02
PARTS LIST.....P03
- ◉ TRAVELLING STEADYQ01/Q02
PARTS LIST.....Q03
- ◉ CHIP COVERR01/R02
PARTS LIST.....R03

HEADSTOCK ASSEMBLY (E.V.S. MODEL)




HEADSTOCK ASSEMBLY 1


(E.V.S. MODEL)




HEADSTOCK ASSEMBLY 2 (E.V.S. MODEL)



HEADSTOCK ASSEMBLY 3 (E.V.S. MODEL) 64



HEADSTOCK ASSEMBLY 4 (E.V.S. MODEL)



HEADSTOCK ASSEMBLY

(E.V.S. MODEL)

ERL-13-01

Page 1/2

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|-----------------------|------|-----------------|---------|-----------|-----------------------|------|--------------------------|
| 1 | | Oil Cover | 1 | 3/4" | 43 | 20029 | Lever | 2 | 搖臂 |
| 2 | | Hex. socket head bolt | 10 | CAP 6x40 | 44 | | Key | 2 | 3x3x18 鍵 |
| 3 | 10057 | Head stock cover | 1 | 主軸箱蓋 | 45 | 20009 | Shaft | 1 | 心軸 |
| 4 | 10057-P | Packing | 1 | 石棉墊 | 46 | 20005 | Shaft | 1 | 心軸 |
| 5 | | Tube | 1 | 銅管 ϕ 6x270 | 47 | | "O" ring | 2 | P16 O形環 |
| 6 | | Washer | 1 | M10 | 48 | 20017 | Collars | 2 | 軸座 |
| 7 | 20018 | Fork | 1 | 撥塊 | 49 | | Hex. socket head bolt | 6 | CAP 5x15 |
| | | | | | 50 | 20021 | Handle | 2 | 把手 |
| 9 | | Clip | 3 | E8 扣環 | 51 | RML-20022 | Spring | 2 | 彈簧 |
| 10 | | Hex. socket head bolt | 7 | CAP 6x10 | 52 | 20026 | Washer | 2 | 墊圈 |
| 11 | 20001 | Lever frame | 1 | 搖臂支架 | 53 | | Spring washer | 4 | M12彈簧墊圈 |
| 12 | | Set screw | 2 | PT3/8 | 54 | | Hex. socket head bolt | 4 | M12x40 |
| | | | | | 55 | | Oil sight | 1 | 3/4" |
| | | | | | 56 | 20022 | Shaft | 1 | G軸 |
| 20 | | Hex. socket head bolt | 4 | CAP 4x10 | 57 | | "O" ring | 1 | P14 O形環 |
| 21 | 20023 | Gear | 2 | 40T 齒輪 | 58 | 20020 | Dever | 1 | 大叉臂 |
| 22 | 20002 | Housing | 1 | 固定體 | 59 | | Clip | 1 | S16 扣環 |
| 23 | | Hex. socket head bolt | 3 | CAP6x20 | 60 | 20016 | Fork | 1 | 撥塊 |
| 24 | | "O" ring | 2 | P44 O形環 | 61 | | Oil seal | 1 | 油封30x62x12 |
| 25 | 20003 | Range selector | 1 | 目轉盤 | 62 | 10032 | Washer | 1 | 墊圈 |
| 26 | | Hex. socket head bolt | 2 | CAP 5x10 | 63 | | Spring washer | 1 | M8彈簧墊圈 |
| 27 | 20028 | Handle | 1 | 手柄 | 64 | | Hex. socket head bolt | 1 | CAP 8x25 |
| 28 | | Steel ball | 4 | ϕ 1/4" | | | | | |
| 29 | 20052 | Spring | 1 | 彈簧 | | | | | |
| 30 | | Set screw | 6 | SET 8x8 | | | | | |
| 31 | 20004-V | Speed selector | 1 | 速度選擇器 | | | | | |
| | | | | | | | | | |
| 33 | | Rivet | 8 | ϕ 2 | 71 | 10023 | Plug | 1 | 端塞 |
| 34 | | Key | 1 | 6x6x14 鍵 | 72 | | "O" ring | 1 | P55 O形環 |
| 35 | 20008 | Shaft | 1 | F軸 | 73 | | Clip | 1 | S30 扣環 |
| 36 | | "O" ring | 1 | P18 O形環 | 74 | | Ball bearing | 2 | 6206培林 |
| 37 | 20024 | Washer | 1 | 墊圈 | 75 | | Clip | 3 | S38扣環 |
| 38 | | Hex. socket head bolt | 16 | CAP 6x16 | 76 | 10013 | Driving shaft | 1 | B軸 |
| 39 | 40071 | Plug | 1 | 蓋子 | 77 | 10019 | Gear(22T) | 1 | Assembly for replacement |
| 40 | RML-20028 | Spring | 1 | 彈簧 | | | Key(10x8x20L) | 2 | |
| 41 | RML-20044 | Fork | 1 | 撥塊 | | 10020 | Gear(76T) | 1 | |
| 42 | | Clip | 2 | S15 扣環 | | | Clip(S50) | 1 | |

HEADSTOCK ASSEMBLY


(E.V.S. MODEL)

ERL-13-01


Page 2/2

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|-----------------------|------|---------------|---------|-----------|------------------|------|--------------------------|
| 81 | 10017-V | Gear | 1 | 33T 齒輪 | | | | | |
| 82 | | Ball bearing | 1 | 6205 培林 | | | | | |
| 83 | | Clip | 4 | S25 扣環 | 121 | 10077-V | Minor tip | 1 | 檢出端柱 |
| 84 | 10022 | Cover | 1 | 端蓋 | 122 | 10074-V | Balance ring | 1 | 固定環 |
| 85 | | Clip | 2 | S20 扣環 | 123 | | Set screw | 1 | M10x10L |
| 86 | | Ball bearing | 1 | 6304 培林 | 124 | | Spring pin | 1 | Ø3x15L |
| | | | | | 125 | 10068 | Extend collar | 1 | 軸環 |
| 88 | 10028 | Gear | 1 | 38T齒輪 | 126 | RML-10038 | Washer | 2 | 墊圈 |
| | | | | | | | Key(6x6x16L) | 1 | |
| 90 | 10025 | Gear Shaft | 1 | 16T A軸 | | 10049 | Gear(21T) | 1 | Assembly for replacement |
| 91 | | Key | 1 | 7x7x104 鍵 | | 10050 | Gear(42T) | 1 | |
| 92 | | Key | 1 | 7x7x53 鍵 | | | Clip(S35) | 1 | |
| 93 | | "O" ring | 1 | P75 O形環 | | | | | |
| 94 | 10024 | Flange bearing | 1 | 承軸殼 | 130 | | "O" ring | 3 | P21 扣環 |
| 95 | | Clip | 1 | R62 扣環 | 131 | 10034 | Shaft | 1 | D心軸 |
| 96 | 10031-V | Pulley | 1 | V型皮帶輪 | 132 | 10039 | Washer | 3 | 墊圈 |
| 97 | 10001 | Head stock | 1 | 主軸箱 | | | Clip(S35) | 1 | |
| 98 | 10002 | Spindle | 1 | 主軸 | | 10048 | Gear(21T) | 1 | Assembly for replacement |
| 99 | 10003 | Plunger | 3 | 固定銷 | | | Key(6x6x15L) | 1 | |
| 100 | 10005 | Cam spring | 3 | 壓縮彈簧 | | 10047 | Gear(42T) | 1 | |
| 101 | | Hex. socket head bolt | 3 | 5/16"x18x16mm | | | | | |
| 102 | 10004 | Cams | 3 | 偏心鎖緊銷 | 136 | 10036 | Washer | 3 | 墊圈 |
| 103 | | Key | 2 | 10x6x45 鍵 | 137 | 10035 | Shaft | 1 | E心軸 |
| 104 | | Key | 1 | 7x7x35 鍵 | 138 | RML-10046 | Gear | 1 | 21T |
| 105 | | Hex. socket head bolt | 3 | CAP 6x30 | 139 | 10033 | Shaft | 1 | F心軸 |
| 106 | 10007 | Front bearing cover | 1 | 前蓋 | | | | | |
| 107 | 10007-P | Packing F | 1 | 石棉墊 | 141 | RML-10051 | Gear | 1 | 21T齒輪 |
| 108 | | Ball bearing | 1 | 30213 培林 | 142 | 10037 | Washer | 2 | 止推圈 |
| 109 | 10008 | Gear | 1 | 72T 齒輪 | 143 | | Needle bearing | 2 | RNA-6904 培林 |
| 110 | 10009 | Gear | 1 | 41T 齒輪 | 144 | 10041 | Flange bearing | 1 | 軸承套 |
| 111 | | Clip | 1 | S60 扣環 | 145 | RML-10040 | Shaft | 1 | G心軸 |
| 112 | 10010 | Gear | 1 | 42T 齒輪 | | | | | |
| 113 | | Clip | 1 | S56 扣環 | 147 | | Oil seal | 1 | 油封28x44x07 |
| 114 | | Ball bearing | 1 | 32011 培林 | 148 | | Square head plug | 1 | 1/2" |
| 115 | 10011 | Nut | 1 | 螺帽 | 149 | 61001-V | Name plate | 1 | |
| 116 | 10012-P | Packing O | 1 | 石棉墊 | | | | | |
| 117 | 10012 | Outside cover | 1 | 後蓋 | | | | | |


GEARBOX ASSEMBLY (For ERL-13")



GEARBOX ASSEMBLY 1



GEARBOX ASSEMBLY 2 (For ERL-13")



GEARBOX ASSEMBLY

ERL-13-02

Page 1/2

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|-----------------|------|-----------|---------|-----------|-----------------|------|----------|
| 1 | 30003 | Shaft | 1 | | 38 | 30029 | Gear | 1 | 28T |
| 2 | | Oil seal | 1 | 20x32x05 | 39 | 30030 | Gear | 1 | 26T |
| 3 | | Bearing | 2 | TAF202820 | 40 | 30031 | Gear | 1 | 38T |
| 4 | 30005 | Flanged bearing | 1 | | 41 | 30032 | Nut | 1 | |
| 5 | 30016 | Washer | 1 | | 42 | | Clip | 1 | S22 |
| 6 | | Clip | 5 | S20 | 43 | 30034 | Gear | 1 | 36T/50T |
| 7 | | Key | 1 | 7x7x35 | 44 | 30037 | Gear | 1 | 22T |
| 8 | 30007 | Gear | 1 | 19T/20T | 45 | 30038 | Gear | 1 | 22T |
| 9 | 30008 | Shaft | 1 | | 46 | 30039 | Gear | 1 | 22T |
| 10 | 30018 | Cover | 1 | | 47 | 30040 | Gear | 1 | 33T |
| 11 | | Bearing | 3 | 16004 | 48 | 30041 | Gear | 1 | 22T |
| 12 | 30006 | Washer | 1 | | 49 | | Clip | 1 | S17 |
| 13 | 30020 | Gear | 1 | 19T/30T | 50 | 30042 | Gear | 1 | 20T/36T |
| 14 | 30021 | Washer | 1 | | 51 | 30016 | washer | 1 | |
| 15 | | Clip | 1 | S25 | 52 | 30017 | Flanged bearing | 1 | |
| 16 | 30019 | Shaft | 1 | | 53 | | Oil seal | 1 | 20x32x05 |
| 17 | 30036 | Shaft | 1 | | 54 | 30014 | Shaft | 1 | |
| 18 | | Woodruff key | 1 | 5xψ19 | 55 | 30035 | Flanged bearing | 1 | |
| 19 | 30018-P | Oil seal | 1 | | 56 | | Oil seal | 1 | 24x35x08 |
| 20 | 30001 | Gearbox body | 1 | | 57 | 30033 | Shaft | 1 | |
| 21 | | Bearing | 3 | 16004 | 58 | | Key | 1 | 5x5x35 |
| 22 | 30009 | Gear | 1 | 38T | 59 | | Bearing | 1 | 6001 |
| 23 | 30010 | Gear | 1 | 23T/19T | 60 | | Clip | 1 | S12 |
| 24 | 30011 | Washer | 1 | | 61 | 30043 | Flanged bearing | 1 | |
| 25 | | Clip | 6 | R40 | 62 | 30002-P | Seal | 1 | |
| 26 | | Bearing | 3 | 6203 | 63 | 30084 | Partition nut | 2 | |
| 27 | 30012 | Clutch | 1 | | 64 | 30077 | Upper plate | 2 | |
| 28 | 30013 | Washer | 1 | | 65 | 30082 | Fort support | 1 | |
| 29 | | Clip | 1 | S16 | 66 | 30070 | Spring | 4 | φ 4x19 |
| 30 | 30015 | Gear | 1 | 35T | 67 | | Steel ball | 3 | 1/4" |
| 31 | 30022 | Gear | 1 | 22T | 68 | 30079 | Partition | 3 | |
| 32 | 30023 | Gear | 1 | 19T | 69 | 30080 | Fort support | 1 | |
| 33 | 30024 | Gear | 1 | 20T | 70 | 30078 | Fort support | 1 | |
| 34 | 30025 | Gear | 1 | 24T | 71 | 30081 | Fort support | 1 | |
| 35 | 30026 | Gear | 1 | 23T | 72 | 30087 | Reverse-stop | 1 | |
| 36 | 30027 | Gear | 1 | 27T | 73 | 30085 | Spacer | 2 | |
| 37 | 30028 | Gear | 1 | 24T | 74 | 30086 | Shoulder plate | 1 | |

GEARBOX ASSEMBLY


ERL-13-02

Page 2/2


| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
|---------|-----------|------------------|-----|---------|---------|-----------|------------------------|-----|------------|
| 75 | 30100 | Fixed plate A | 1 | | 111 | 30088 | Selector lever | 1 | |
| 76 | 30083 | Fixed plate B | 1 | | 112 | | O-ring | 2 | G40 |
| 77 | 30053 | Fork | 1 | | 113 | 30066 | Selector lever support | 1 | |
| 78 | 30055 | Fork | 1 | | 114 | 30069 | Spring | 1 | φ 9x38 |
| 79 | 30054 | Fork | 1 | | 115 | 30068 | Selector lever | 1 | |
| 80 | 30053 | Fork | 1 | | 116 | | O-ring | 1 | G30 |
| 81 | | Spring pin | 8 | φ 3x16 | 117 | 30067 | Selector lever cover | 1 | |
| 82 | 30061 | Shaft | 1 | | 118 | 30076 | Specifying base | 1 | |
| 83 | 30065 | Arm | 1 | | 119 | 30071 | Handle | 3 | |
| 84 | 30060 | Cam | 1 | | 120 | 30072 | Washer | 3 | |
| 85 | 30059 | Support seat | 1 | | 121 | 30073 | Plug | 3 | |
| 86 | | Clip | 2 | E8 | 122 | | Oil sight | 1 | |
| 87 | 30058 | Washer | 1 | | 123 | 61022 | Switch plate | 1 | |
| 88 | | Clip | 2 | S17 | | | | | |
| 89 | | Woodruff key | 2 | 4xψ13 | | | | | |
| 90 | 30057 | Shaft | 1 | | | | | | |
| 91 | 30047 | Pad | 1 | | 201 | | Hex. socket head bolt | 14 | M6x12L |
| 92 | 30062 | Pin | 2 | φ 5 | 202 | | Hex. socket head bolt | 4 | M5x20L |
| 93 | 30063 | Fork | 1 | | 203 | | Spring washer | 4 | M6 |
| 94 | | Steel ball | 1 | 1/4" | 204 | | Hex. socket head bolt | 2 | M6x12L |
| 95 | 30049 | Spring | 1 | φ 4x19 | 205 | | Hex. socket head bolt | 2 | M6x35L |
| 96 | 30046 | Pad | 1 | | 206 | | Spring pin | 2 | φ 4x24 |
| 97 | 30048 | Lever | 1 | | 207 | | Set screw | 2 | M6x8L |
| 98 | 30099 | Spring | 2 | φ 6x13 | 208 | | Hex. socket head bolt | 4 | M6x20L |
| 99 | | Steel ball | 2 | 1/4" | 209 | | Hex. socket head bolt | 6 | M6x70L |
| 100 | 30052 | Selector bar | 1 | | | | | | |
| 101 | | Woodruff key | 2 | 4xψ13 | 211 | | Hex. socket head bolt | 3 | M5x25L |
| 102 | 30050 | Shaft | 2 | | 212 | | Hex. socket head bolt | 3 | M6x12L |
| 103 | | O-ring | 2 | P18 | 213 | | Hex. socket head bolt | 3 | M5x12L |
| 104 | 30051 | Bush | 2 | | 214 | | Dome cross screw | 5 | M4x6L |
| 105 | 30045 | Fork | 1 | | 215 | | Hex. socket head bolt | 4 | M8x65L |
| 106 | | Spring pin | 12 | φ 5x16 | 216 | | Taper pin | 2 | #7x3 1/4"L |
| 107 | | Square head plug | 1 | 1/2" | | | | | |
| 108 | | Elbow | 1 | 1/2" | | | | | |
| 109 | | Nipple | 1 | 1/2"x1" | | | | | |
| 110 | 30002-A | Gearbox cover | 1 | | | | | | |

2009.08

APRON(L.H) ASSEMBLY



APRON(L.H) ASSEMBLY



APPRON(L.H) ASSEMBLY

ERL-13-03


Page 1/2

| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
|---------|-----------|--------------|-----|-------------------|---------|-----------|----------------|-----|--------------|
| 1 | 40014 | Gear | 1 | 18T/60T | 37 | | Spring | 1 | ϕ 4x19 |
| 2 | | Washer | 2 | AS3047 | 38 | 50015 | Bracket | 1 | |
| 3 | | Spring pin | 1 | ϕ 4x22 | 39 | 40003 | Gear shaft | 1 | 18T |
| 4 | 40015 | Gear | 1 | 81T/60T | 40 | | Woodruff key | 1 | 19x ϕ 5 |
| 5 | | Pin | 3 | ϕ 4x17 | 41 | 40004-M | Shaft liner | 1 | for Metric |
| 6 | 40017 | Gear | 1 | 72T/60T | | 40004-I | | | for Imperial |
| 7 | 40060 | Collar | 1 | | 42 | 40005-M | Index ring | 1 | for Metric |
| 8 | 40071 | Plug | 1 | | | 40005-I | | | for Imperial |
| 9 | 40023 | Gear bracket | 1 | | | | | | |
| 10 | | Oil cap | 1 | | 44 | 40016 | Spring | 3 | |
| 11 | 40019 | Cam shaft | 1 | | 45 | 40007 | Handle wheel | 1 | |
| 12 | 40020 | Handle | 1 | | 46 | 40011 | Plug | 1 | |
| 13 | 40018 | Shaft | 1 | | 47 | 40009 | Handle | 1 | |
| 14 | | Stell ball | 7 | 1/4" | 48 | 40017 | Screw | 1 | |
| 15 | 40016 | Spring | 2 | ϕ 6x13 | 49 | 40078 | Safety plate | 1 | |
| 16 | 40013 | Gear shaft | 1 | 16T | 50 | 40077 | Plate | 1 | |
| 17 | | Key | 1 | 5x5x18 | 51 | 40034 | Bevel gear | 1 | 23T |
| 18 | 40012-M | Gear | 1 | 82T(for Metric) | 52 | | Thrust bearing | 1 | NTB/AS-2542 |
| | 40012-I | | | 81T(for Imperial) | 53 | 40001-L | Apron(L.H) | 1 | |
| 19 | | Spring pin | 1 | ϕ 5x36 | | 40001-R | Apron(R.H) | | |
| 20 | | Oil sight | 1 | | 54 | | Bearing | 1 | NK29/30 |
| 21 | | Clip | 1 | S16 | 55 | 40032 | Washer | 1 | |
| 22 | 40067 | Gear | 3 | 18T | 56 | | Clip | 1 | S25 |
| 23 | | O-ring | 2 | P18 | | | | | |
| 24 | 40068 | Shaft | 1 | | 58 | 40066 | Gear | 1 | 18T |
| 25 | | Spring pin | 1 | ϕ 4x24 | 59 | | Spring pin | 1 | ϕ 5x22 |
| 26 | 40063-L | Fork(L.H) | 1 | | | | | | |
| | 40073-R | Fork(R.H) | | | 61 | 40065 | Gear | 1 | 18T |
| 27 | 40062 | Shaft | 1 | | 62 | 40035 | Washer | 1 | |
| 28 | | O-ring | 2 | P16 | 63 | 40033 | Bevel gear | 1 | 64T |
| 29 | | O-ring | 1 | P26 | | | | | |
| 30 | 40061 | Shaft liner | 1 | | 65 | | Woodruff key | 2 | 4x ϕ 13 |
| 31 | 40076 | Knob | 1 | | 66 | 40031 | Shaft | 1 | |
| 32 | 40025-L | Plate(L.H) | 1 | | 67 | 49001-L | Oil fence | 1 | |
| | 40024-R | Plate(R.H) | | | 68 | 40037 | Handle | 1 | |
| 34 | | O-ring | 2 | P12 | 69 | 40038 | Hub | 1 | |
| 35 | 40064 | Shaft | 1 | | 70 | | Spring | 1 | ϕ 6x27 |


[illegible]

Page 2/2


DIAL INDICATOR ASSEMBLY



DIAL INDICATOR ASSEMBLY METRIC (LEADSCREW PITCH 6)




DIAL INDICATOR ASSEMBLY IMPERIAL (LEADSCREW 4 T.P.I.)




ERL-13-04

Page 1/1


4 WAY TOOL POST



4 WAY TOOL POST (METRIC)




4 WAY TOOL POST (IMPERIAL)




| 4 Way Tool Post (METRIC) | | | | | 4 Way Tool Post (IMPERIAL) | | | | |
|-----------------------------|-----------|-------------------------|-----|--------------|-------------------------------|-----------|------------------------------|-----|--------------|
| | | | | | ERL-13-05 Page 1/1 | | | | |
| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
| 1 | 50067 | Handle | 1 | | 1 | 50067 | Handle | 1 | |
| 2 | 50066 | Turret nut | 1 | | 2 | 50066 | Turret nut | 1 | |
| 3 | 50065 | Collar | 1 | | 3 | 50065 | Collar | 1 | |
| 4 | 50068 | Bolt | 12 | | 4 | 50068 | Bolt | 12 | |
| 5 | 50060 | Turret body | 1 | | 5 | 50060 | Turret body | 1 | |
| 6 | 50062 | Turret shaft | 1 | | 6 | 50062 | Turret shaft | 1 | |
| 7 | 50064 | Pin | 1 | | 7 | 50064 | Pin | 1 | |
| 8 | 50043 | Spring | 1 | Ø6x27 | 8 | 50043 | Spring | 1 | Ø6x27 |
| | | | | | 9 | 50061 | T Nut | 1 | |
| 10 | 50005 | Solid topslide | 1 | | 10 | 50006 | Solid topslide | 1 | |
| 11 | 50056 | Gib | 1 | | 11 | 50056 | Gib | 1 | |
| 12 | 50054 | Screw | 1 | | 12 | 50054 | Screw | 1 | |
| 13 | 14-50004 | Swivel slide | 1 | | 13 | 14-50004 | Swivel slide | 1 | |
| 14 | 50038-M | Nut(for METRIC P=2mm) | 1 | Assembly for | 14 | 50038-I | Nut(for INCH P=0.1") | 1 | Assembly for |
| 15 | 50042-M | Screw(for METRIC P=2mm) | 1 | replacement | 15 | 50042-I | Screw(for INCH P=0.1") | 1 | replacement |
| 16 | | Trust bearing | 2 | 51101 | 16 | | Trust bearing | 2 | 51101 |
| | | | | | 17 | 50063 | Curve pilot | 1 | |
| 18 | 50041 | Keep assy | 1 | | 18 | 50041 | Keep assy | 1 | |
| 19 | 50044-M | Dial 100dividing | 1 | for METRIC | 19 | 50044-I | Dual dial 100div/I, 127div/M | 1 | for INCH |
| 21 | 50111 | Bush | 1 | | 20 | 50111 | Bush | 1 | |
| 22 | 50045 | Handle wheel | 1 | | 21 | 50045 | Handle wheel | 1 | |
| 23 | 50047 | Handle | 1 | | 22 | 50047 | Handle | 1 | |
| 24 | 50070 | T wrench | 1 | | 23 | 50070 | T wrench | 1 | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 51 | | Hex. socket head bolt | 1 | M6x10L | 51 | | Hex. socket head bolt | 1 | M6x10L |
| 52 | | Set screw | 2 | M6x8L | 52 | | Set screw | 2 | M6x8L |
| 53 | | Hex. socket head bolt | 2 | M6x20L | 53 | | Hex. socket head bolt | 2 | M6x20L |
| | | | | | 54 | | Rivet | 2 | φ 2 |
| | | | | | 55 | | Set screw | 2 | M8x12L |
| 56 | | Oil ball | 1 | 1/4" | 56 | | Oil ball | 1 | 1/4" |
| 57 | | Steel ball | 1 | 1/4" | 57 | | Steel ball | 1 | 1/4" |
| 58 | | Set screw | 1 | M8x10L | 58 | | Set screw | 1 | M8x10L |
| 59 | | Set screw | 3 | M6x8L | 59 | | Set screw | 2 | M6x8L |
| | | | | | | | | | |


SADDLES ASSEMBLY



SADDLES ASSEMBLY 1



SADDLES ASSEMBLY 2



SADDLES ASSEMBLY

ERL-13-06

Page 1/2

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|----------------------------|------|------------------------|---------|-----------|------------------------------|------|-------------------------|
| 1 | 00AS16M6 | Adjust screw | 6 | | 33 | 50031-M | Dial 250dividing | 1 | for METRIC |
| 2 | 50003 | Cross slide 1416 | 1 | | | 50030-I | Dual dial 200div/I, 254div/M | 1 | for IMPERIAL |
| 3 | 50036 | Pivot | 1 | ϕ 18x28 | 34 | 50029 | Hand wheel | 1 | |
| 4 | 50037 | T bolt | 2 | | 35 | 50033 | Fix screw | 1 | M12xP1.75 |
| 5 | 50023 | Gib-X | 1 | | 36 | 50035 | Handle | 1 | |
| 6 | 50070 | Wiper-X | 1 | | 37 | 50034 | Bolt | 1 | |
| 7 | 50069 | Plate -X | 1 | | 38 | 50053 | Gib-Z | 2 | |
| 8 | | Trust bearing | 2 | NTB/AS2 1226 | 39 | 50052 | Front anti-floater | 1 | |
| 9 | 50026 | Cap collar | 2 | | 40 | 50055 | Rear anti-floater | 1 | |
| 10 | 50017 | Washer | 1 | | 41 | 50013 | Washer | 1 | ϕ 6.5x ϕ 15x3 |
| 11 | 50021 | Wedge | 1 | 7x7x30 | 42 | 50011 | Gear | 1 | 16T |
| 12 | 50019-M | Nut(for METRIC P=2.5mm) | 1 | Assembly for | 43 | 50012 | Short shaft | 1 | |
| 13 | 50016-M | Screw(for METRIC P=2.5mm) | 1 | replacement | 44 | | Straight adapter | 2 | PT 1/8x ϕ 4 |
| 12' | 50019-I | Nut(for IMPERIAL P=0.1") | 1 | Assembly for | 45 | | AL. tube | 1 | ϕ 4x260 |
| 13' | 50016-I | Screw(for IMPERIAL P=0.1") | 1 | replacement | 46 | | Elbow adapter | 2 | PT 1/8x ϕ 4 |
| 14 | | Key | 1 | 3x3x80 | 47 | | AL. tube | 1 | ϕ 4x120 |
| 15 | | Spring pin | 2 | ϕ 5x40 | 48 | | Oil filter | 1 | ϕ 6 |
| 16 | | Spraying pipe | 1 | PT3/8 x 24" | 49 | | AL. tube | 1 | ϕ 6x160 |
| 17 | | Valve & junction assy. | 1 | PT3/8 | 50 | | Straight adapter | 2 | PT 1/8x ϕ 6 |
| 18 | 50018 | Bracket | 1 | | 51 | | Lubricator assy. | 1 | |
| 19 | 50001 | Saddle 1416 | 1 | | 52 | 50058 | Clamp plate | 1 | |
| 20 | 50050 | Wiper F | 2 | | 53 | 50077 | Plate | 1 | |
| 21 | 50051 | Plate F | 2 | | 54 | | Key | 1 | 3x3x15 |
| 22 | | Oil cover | 1 | NF 3/4" | | | | | |
| 23 | | Taper Pin | 2 | #6x2 1/2"L | | | | | |
| 24 | 50048 | Wiper V | 2 | | | | | | |
| 25 | 50049 | Plate V | 2 | | | | | | |
| 26 | 50014 | Pinion | 1 | 160DP 16T | | | | | |
| 27 | 50015 | Keep assy. | 1 | | | | | | |
| 28 | | Steel ball | 4 | 1/4" | 101 | | Oil ball | 2 | 1/4" |
| 29 | 50032 | Spring | 4 | ϕ 6x15 L | 102 | | Set screw | 2 | M6x30L |
| 30 | | Trust bearing | 2 | NTB/AS2 1730 | 103 | | Hex. socket head bolt | 4 | M6x30L |
| 31 | 50030 | Washer | 1 | ϕ 18x ϕ 52x4 | 104 | | Nut | 2 | M10 |
| 32 | 50027-M | Dial ring | 1 | for METRIC | 105 | | Washer | 2 | M10 |
| | 50027-I | Dial ring | 1 | for IMPERIAL | 106 | | Dome cross screw | 13 | M5x12L |


2009.08

| | |
|------------------|-----------------------|
| SADDLES ASSEMBLY | ERL-13-06 Page 2/2 |
|------------------|-----------------------|


Page 2/2

[illegible]

BED & SHAFTS ASSEMBLY



BED & SHAFTS ASSEMBLY



ERL-13-07

BED & SHAFTS ASSEMBLY


ERL-13-07

Page 1/1

| KEY NO | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|--------|-----------|-----------------------|------|----------------------|--------|--------------|-----------------------|------|------------|
| 1 | 63001-30 | Bed | 1 | 30" | 32 | | Clip | 1 | S32 |
| | 63001-40 | Bed | 1 | 40" | 33 | 63014-30 | Third rod shaft | 1 | |
| 2 | 63038 | Bolt | 1 | | | 63014-40 | Third rod shaft | 1 | |
| 3 | | Hexagon head bolt | 8 | M12x45L | 34 | 63012 | Stopper | 1 | |
| 4 | | Washer | 8 | φ 12x φ 20x3t | 35 | | Hex. socket head bolt | 1 | M6x20L |
| 5 | | Hex. socket head bolt | 9 | M6x20L | 36 | 63016 | Clutch collar | 1 | |
| 6 | | Spring pin | 6 | φ 6x25L | 37 | 63013 | Bush | 1 | |
| 7 | 63025 | Nut | 1 | | 38 | | Taper pin | 1 | #4x1 1/4"L |
| 8 | | Set screw | 2 | M6x8L | 39 | | Thrust bearing | 1 | 51203 |
| 9 | | Thrust bearing | 2 | 51203 | 40 | | Key | 2 | 5x5x15 |
| 10 | 63026 | Bracket | 1 | | 41 | 63006 | Spring cover | 1 | |
| 11 | | Oil ball | 2 | 1/4" | 42 | 63007 | Spring | 1 | |
| 12 | 63037 | Plug | 1 | | 43 | | Clip | 1 | S32 |
| 13 | | Set screw | 1 | M12x12L | 44 | 63010 | Shear pin | 1 | |
| 14 | 63041 | Spring | 1 | | 45 | 63008 | Shroud washer | 1 | |
| 15 | | Steel ball | 1 | 3/8" | 46 | 63009 | Collar | 1 | |
| 16 | | Hexagon head bolt | 2 | M8x35L | 47 | | Set screw | 1 | M6x6L |
| 17 | | Taper pin | 2 | #6x2"L | 48 | 63042 | Spring | 4 | φ 8x32 |
| 17 | 63630 | Knob | 1 | | | 63023-40 | 30"Rack | 1 | |
| 19 | 63022 | Handle | 1 | | 49 | RML-63023-60 | 40"Rack | 1 | |
| 20 | | Nut | 1 | M12xP1.75 | | | | | |
| 21 | 63021 | Pin | 2 | | 50 | 63024-GL | 30"Rack | 1 | |
| 22 | | Thrust bearing | 1 | NTB/AS2 1831 | | | 40"Rack | 1 | |
| 23 | 63020 | Lever assy | 1 | | 51 | | Set screw | 1 | M8x12L |
| 24 | 63043 | Collar | 1 | | 52 | 60037 | Pin | 1 | |
| 25 | | Set screw | 1 | M6x8L | 53 | 60042 | Lever | 1 | |
| 26 | 63005-30M | 30"Lead screw | 1 | for METRIC P=6mm | 54 | | Clip | 1 | E6 |
| | 63005-30I | 40"Lead screw | 1 | for IMPERIAL 4T.P.I. | 55 | 60036 | Shaft | 1 | |
| | 63005-40M | 40"Lead screw | 1 | for METRIC P=6mm | 56 | 17-61044 | Switch base | 1 | |
| | 63005-40I | 40"Lead screw | 1 | for IMPERIAL 4T.P.I. | 57 | | Limit switch | 2 | TM1308 |
| 27 | 63011-30" | Feed rod | 1 | | 58 | | Hex. socket head bolt | 1 | M6x16L |
| | 63011-40" | Feed rod | 1 | | 59 | 60041 | Collar | 1 | |
| 28 | 63015 | Third rod bracket | 1 | | 60 | | Hex. socket head bolt | 1 | M6x10L |
| 29 | 63019 | Sleeve | 1 | | 61 | | Done cross screw | 2 | M6x10L |
| 30 | 63018 | Spring | 1 | | 62 | 17-61046 | Plate | 1 | |
| 31 | 63017 | Spring cover | 1 | | | | | | |


2009.08

END GEAR ASSEMBLY




END GEAR -- METRIC (LEADSCREW PITCH 6)

| KEY NO. | PARTS No. | PARTS NAME | Q'TY | REMARK |
|---------|------------|-----------------------|------|-----------|
| 1 | | Hex. socket head bolt | 1 | M6x20 |
| 2 | 60022 | Washer | 1 | |
| 3 | 13-60001-M | Gear | 1 | M2,28T |
| 4 | 14-60017 | Swing frame | 1 | |
| 5 | | Key | 2 | 7x7x15L |
| 6 | | Nut | 2 | M14xP2.0 |
| 7 | 60023 | Washer | 3 | |
| 8 | | Clip | 2 | R47 |
| 9 | 13-60002-M | Gear | 1 | M2,54T/5T |
| 10 | | Ball bearing | 2 | 6005 |
| 11 | 60020 | Washer | 1 | |
| 12 | 60013 | Shaft collar | 1 | |
| 13 | 60015 | Gear shaft | 1 | |
| 14 | | Key | 1 | 7x7x30L |
| 15 | 60018 | Stud | 1 | |
| 16 | | Hex. socket head bolt | 1 | M8x20 |
| 17 | 60021 | Washer | 1 | |
| 18 | 13-60004-M | Gear | 1 | M2,64T |
| 19 | 13-60005-M | Gear | 1 | M2,22T |




END GEAR -- IMPERIAL (LEADSCREW 4 T.P.I.)

| KEY NO. | PARTS No. | PARTS NAME | Q'TY | REMARK |
|---------|------------|-----------------------|------|------------|
| 1 | | Hex. socket head bolt | 1 | M6x20 |
| 2 | 60022 | Washer | 1 | |
| 3 | 13-60007-I | Gear | 1 | M2,24T |
| 4 | 14-60017 | Swing frame | 1 | |
| 5 | | Key | 2 | 7x7x15L |
| 6 | | Nut | 2 | M14xP2.0 |
| 7 | 60023 | Washer | 3 | |
| 8 | | Clip | 2 | R47 |
| 9 | 13-60008-I | Gear | 1 | M2,44T/56T |
| 10 | | Ball bearing | 2 | 6005 |
| 11 | 60020 | Washer | 1 | |
| 12 | 60013 | Shaft collar | 1 | |
| 13 | 60015 | Gear shaft | 1 | |
| 14 | | Key | 1 | 7x7x30L |
| 15 | 60018 | Stud | 1 | |
| 16 | | Hex. socket head bolt | 1 | M8x20 |
| 17 | 60021 | Washer | 1 | |
| 18 | 13-60010-I | Gear | 1 | M2,57T |
| 19 | 60016 | Collar | 2 | |




MAIN MOTOR ASSEMBLY

(E.V.S. MODEL &
FRONT MOVEABLE CHIP TRAY)



MAIN MOTOR ASSEMBLY (E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY)



MAIN MOTOR ASSEMBLY


ERL-13-09

(E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY)


Page 1/1

| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
|---------|-----------|-----------------------|-----|------------|---------|-----------|-----------------------|-----|----------------|
| 1 | 61003 | Cover | 1 | | 37 | | Limit switch | 1 | Tm-1704 |
| 2 | 60056 | Nut | 1 | | 38 | | Dome cross screw | 2 | M4x30L |
| 3 | | V belt | 3 | B76 | 39 | 63043 | Block | 6 | |
| 4 | 60055 | Bolt | 1 | | 40 | | Hexagon head bolt | 6 | M16x50L |
| 5 | | Nut | 5 | M10xP1.5 | 41 | 61018 | Plate | 1 | |
| 6 | | Dome cross screw | 8 | M6x10L | 42 | | Hex. socket head bolt | 5 | M6x10L |
| 7 | 61017 | Cover | 1 | | 43 | | Washer | 5 | Ø6xØ16 |
| 8 | | Nut | 4 | M8xP1.25 | 44 | 61025 | Cover | 1 | |
| 9 | 60053 | Bolt | 1 | | | | Electrical box | 1 | |
| 10 | 60046 | Spring | 1 | | 45 | | Washer | 2 | M8 |
| 11 | | Hex. socket head bolt | 1 | M8x120L | 46 | | Hex. socket head bolt | 1 | M8x20L |
| 12 | 60043 | Shaft | 1 | | 47 | | Dome cross screw | 2 | M4x40L |
| 13 | 61045TR3 | Plate | 1 | | 48 | | Limit switch | 1 | Tm1307 |
| 14 | | Hex. socket head bolt | 3 | M10x25L | 49 | | Motor(Inverter) | 1 | 2.2kW(3hp) |
| 15 | | Hex. socket head bolt | 2 | M6x16L | 50 | | Hexagon nut | 2 | M3 |
| 16 | 13-60033 | Cam | 1 | | 51 | 61059 | Bracket E | 1 | |
| 17 | 60047 | Lever | 1 | | 52 | | Encoder | 1 | FQP2-1604N-3U2 |
| 18 | 61061 | Fixed plate | 1 | | 53 | | Dome cross screw | 2 | M3x25L |
| 19 | | Washer | 2 | M8 | 54 | | Pipe clip | 2 | Ø10 |
| 20 | | Hex. socket head bolt | 1 | M8x45L | 55 | | Washer | 2 | M5 |
| 21 | | Clip | 1 | E8 | 56 | | Hex. socket head bolt | 2 | M5x10L |
| 22 | 60044 | Washer | | | 57 | 10077-V | Minor tip | 1 | |
| 23 | 60019 | Brake belt | 1 | | 58 | 10074-V | Balance ring | 1 | |
| 24 | 60028 | Pin | 1 | | 59 | | Spring pin | 1 | Ø3x15L |
| 25 | | Taper pin | 1 | #4x1 3/4"L | 60 | | Set screw | 1 | M8x10L |
| 26 | 61045TR3 | Platform | 1 | | | | | | |
| 27 | 10043-V | Motor pully | 1 | | | | | | |
| 28 | | Nut | 8 | M16x2.0 | | | | | |
| 29 | 60031 | Screw | 2 | M16x170L | | | | | |
| 30 | | Washer | 8 | Ø16.5xØ40 | | | | | |
| 31 | 600048 | Rubber ring | 4 | | | | | | |
| 32 | | Hex. socket head bolt | 2 | M6x12L | | | | | |
| 33 | | Nut | 4 | M4xP0.7 | | | | | |
| 34 | | Hex. socket head bolt | 4 | M10x45L | | | | | |
| 35 | | Washer | 8 | M10 | | | | | |
| 36 | 61028A | Bracket | 1 | | | | | | |

CABINET AND PANEL
(E.V.S. MODEL &
FRONT MOVEABLE CHIP TRAY)



CABINET AND PANEL (E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY)



CABINET AND PANEL

ERL-13-10


(E.V.S. MODEL & FRONT MOVEABLE CHIP TRAY)

Page 1/1


| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
|---------|-----------|-----------------------|-----|------------|---------|-----------|-----------------------|-----|----------------|
| 1 | 60032-30 | Shsft(30") | 1 | Model 1330 | 32 | | Knob | 1 | |
| | 60032-40 | Shsft(40") | 1 | Model 1340 | 33 | | Nut | 1 | M12xP1.75 |
| 2 | 61043-30 | Saddle(30") | 1 | Model 1330 | 34 | | Hex. socket head bolt | 1 | M12x20 |
| | 61043-40 | Saddle(40") | 1 | Model 1340 | 35 | 13-10102 | Piovt | 1 | |
| 3 | 13-60039 | Collar | 2 | | 36 | 14-61053 | Chuck safety guard | 1 | |
| 4 | | Hex. socket head bolt | 6 | M6x16 | 37 | | Hex. socket head bolt | 1 | M6x12 |
| 5 | | Hex. socket head bolt | 4 | M10x20 | 38 | | Set screw | 1 | M5x16 |
| 6 | | Hex. socket head bolt | 10 | M6x10 | 39 | 61035 | Chute | 1 | |
| 7 | | Washer | 8 | M6 | 40 | | Coolant conduit | 1 | CT801x3/8"x72" |
| 8 | 61011-30 | Plate(30") | 1 | Model 1330 | 41 | | Nipple | 1 | 3/8"PTx3/8"PH |
| | 61011-40 | Plate(40") | 1 | Model 1340 | 42 | | Coolant pump | 1 | MC6180 |
| 9 | | Hex. socket head bolt | 2 | M6x20 | 43 | 61015 | Coolant tank | 1 | |
| 10 | 60030 | Flanged Bearing | | | 44 | 61019 | Cover | 1 | |
| 11 | 61009 | Bracket | 2 | | | | | | |
| 12 | | Dome cross screw | 10 | M6x10 | | | | | |
| 13 | 61008PR1 | Bracket | 1 | | | | | | |
| 14 | 61008PL1 | Bracket | 1 | | | | | | |
| 15 | | Dome cross screw | 3 | M5x8 | | | | | |
| 16 | 61016 | Guard | 1 | | | | | | |
| 17 | 61008-30 | Sliding tray(30") | 1 | Model 1330 | | | | | |
| | 61008-40 | Sliding tray(40") | 1 | Model 1340 | | | | | |
| 18 | | Flat hexagon screw | 3 | M5x8 | | | | | |
| 19 | 61020 | Plate | 1 | | | | | | |
| 20 | 61053 | Small bracket | 1 | | | | | | |
| 21 | | Set screw | 2 | M8x12 | | | | | |
| 22 | | Nut | 2 | M4xP0.7 | | | | | |
| 23 | | Spring washer | 2 | M6 | | | | | |
| 24 | | Hex. socket head bolt | 2 | M6x12 | | | | | |
| 25 | 61056 | Bracket | 1 | | | | | | |
| 26 | | Limit switch | 1 | Tz9212 | | | | | |
| 27 | | Dome cross screw | 2 | M4x40 | | | | | |
| 28 | | Nut | 3 | M8xP1.25 | | | | | |
| 29 | | Washer | 8 | M8 | | | | | |
| 30 | | Hex. socket head bolt | 5 | M8x20 | | | | | |
| 31 | 61007-30 | Splash guard(30") | 1 | Model 1330 | | | | | |
| | 61007-40 | Splash guard(40") | 1 | Model 1340 | | | | | |

2009.08

CONVENTIONAL TAILSTOCK ASSEMBLY



CONVENTIONAL TAILSTOCK ASSEMBLY




CONVENTIONAL TAILSTOCK ASSEMBLY

ERL-13-11


Page 1/1

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|-------------------------|------|--------------------------|---------|-----------|-----------------------|------|----------|
| 1 | 70004-M | Lead screw,P=2.5mm | 1 | Assembly for replacement | 33 | 70025 | Plate V | 2 | |
| 2 | 70005-M | Nut,P=2.5mm | 1 | | 34 | 70027 | Plate F | 2 | |
| 1' | 70004-I | Lead screw,P=0.1" | 1 | Assembly for replacement | 35 | 70026 | Wiper F | 2 | |
| 2' | 70005-I | Nut,P=0.1" | 1 | | 36 | 70018 | Gib C | 1 | |
| 3 | | key | 1 | 5x5x20L | 37 | 00SP0250 | Spring | 1 | φ 25x45L |
| 4 | | Thrust bearing | 2 | NTB/AS2035 | 38 | 70020 | Clamp block | 1 | |
| 5 | 70007-M | Flange M | 1 | for METRIC | 39 | 70041 | Stud | 1 | M14x110L |
| | 70007-I | Flange I | 1 | for IMPERIAL | | | | | |
| 6 | | Snap ring | 1 | S32 | | | | | |
| 7 | 70006 | washer | 1 | | 101 | | Hex. socket head bolt | 3 | M6x16L |
| 8 | 70008-M | Index ring 125 dividing | 1 | for METRIC | 102 | | Set screw | 1 | M6x12L |
| | 70008-I | Index ring 100 dividing | 1 | for IMPERIAL | 103 | | Hex. socket head bolt | 1 | M6x12L |
| 9 | 70009 | Handwheel | 1 | | 104 | | Hex. socket head bolt | 1 | M8x70L |
| 10 | 70010 | Fixed screw | 1 | | 105 | | Hex. socket head bolt | 2 | S-M8x60L |
| 11 | 70011 | Bolt | 1 | M8x90L | 106 | | Hex. socket head bolt | 1 | M6x8L |
| 12 | 70012 | Handle | 1 | | 107 | | Hex. socket head bolt | 3 | M6x16L |
| 13 | 40016 | Spring | 3 | φ 6.2x16L | 108 | | Dome cross screw | 8 | M5x12L |
| 14 | | Steel ball | 3 | 1/4" | 109 | | Washer | 2 | M10 |
| 15 | 70022 | Clamp lever L | 1 | | 110 | | Hexagon head bolt | 2 | M10x40L |
| 16 | 70013 | Cam shaft L | 1 | | 111 | | Washer | 3 | M14 |
| 17 | 70021 | Clamp lever R | 1 | | 112 | | Hexagon nut | 1 | M14 |
| 18 | 70017 | Cam shaft R | 1 | | 113 | | Hexagon nut | 1 | M8 |
| 19 | | Spring pin | 2 | φ 4x24 | 114 | | Rivet | 4 | φ 2 |
| 20 | 70057 | Dead center | 1 | MT4 | 115 | | Spring washer | 2 | M10 |
| 21 | | Oil ball | 2 | 1/4" | | | | | |
| 22 | 70001 | Tail stock | 1 | | | | | | |
| 23 | 70003 | Quill | 1 | | | | | | |
| 24 | 70014 | Guide key | 1 | | | | | | |
| 25 | 70032-U | Marked plate U | 1 | Assembly for replacement | | | | | |
| 26 | 70032-D | Marked plate D | 1 | | | | | | |
| 27 | 70015 | Pin nut | 2 | | | | | | |
| 28 | 70016 | Pivot block | 1 | | | | | | |
| 29 | 00ST25M8 | Set screw | 1 | | | | | | |
| 30 | 70002 | Base | 1 | | | | | | |
| 31 | 70019 | Gib screw | 2 | M6x φ 16 | | | | | |
| 32 | 70024 | Wiper V | 2 | | | | | | |

5C COLLET CLOSER ATTACHMENT (E.V.S. MODEL)



5C COLLET CLOSER ATTACHMENT (E.V.S. MODEL)



5C COLLET CLOSER ATTACHMENT

ERL-13-12

(E.V.S. MODEL)


Page 1/1

| KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | Q'TY | REMARK |
|---------|-----------|-------------------------------------|------|--------------------------|---------|-----------|------------|------|--------|
| 1 | | Hex. socket head bolt | 3 | M6x25 | | | | | |
| 2 | 90048 | Bracket | 1 | | | | | | |
| 3 | | Nut | 1 | M16 | | | | | |
| 4 | 90049 | Bolt | 1 | | | | | | |
| 5 | 90055 | Bolt | 1 | | | | | | |
| 6 | 90047 | Connector Casting | 1 | | | | | | |
| 7 | | Nut | 2 | W1/2" | | | | | |
| 8 | 90050 | Screw | 1 | W1/2x155mm | | | | | |
| 9 | 90044 | Handle Casting | 1 | | | | | | |
| 10 | 00ST30M8 | Set screw | 2 | | | | | | |
| 11 | | Nut(M8) | 2 | | | | | | |
| 12 | | Nut(1/2"-12UNC) | 1 | | | | | | |
| 13 | 90045 | Handle Rod | 1 | | | | | | |
| 14 | 90046 | Handle | 1 | | | | | | |
| 15 | | Clip(S34) | 1 | | | | | | |
| 16 | | Washer(ϕ 52.4x ϕ 34.4x9) | 1 | | | | | | |
| 17 | 90042 | Nut | 1 | | | | | | |
| 18 | 90038 | Bearing and Retainer | 1 | Assembly for replacement | | | | | |
| 19 | | Ball bearing(6208) | 1 | | | | | | |
| 20 | 90037 | Cam | 1 | | | | | | |
| 21 | | Hex. socket head bolt(M4x8) | 3 | | | | | | |
| 22 | 90043 | Collar | 1 | | | | | | |
| 23 | 90029 | Tube | 1 | | | | | | |
| 24 | 90031 | Finger | 3 | | | | | | |
| 25 | 90032 | Pivot Pin(ϕ 6x40) | 3 | | | | | | |
| 26 | 90035 | Knob | 1 | | | | | | |
| 27 | | Steel ball(ϕ 5mm) | 1 | | | | | | |
| 28 | 90033 | Spring | 1 | | | | | | |
| 29 | | Pin(ϕ 5x18) | 1 | | | | | | |
| 30 | | Hex. socket head bolt | 3 | M5x12 | | | | | |
| 31 | 90025 | Index Ring | 1 | | | | | | |
| 32 | 90023 | Hub | 1 | | | | | | |
| 33 | 90028 | Tube | 1 | | | | | | |
| 34 | 90027 | Pin | 1 | | | | | | |
| 35 | 90026 | Bush | 1 | | | | | | |


2009.08

-L03V-

TAPER ATTACHMENT



TAPER ATTACHMENT



TAPER ATTACHMENT

ERL-13-13


Page 1/1

| KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK | KEY NO. | PARTS NO. | PARTS NAME | QTY | REMARK |
|---------|-----------|-----------------------|-----|--------------|---------|-----------|-----------------------|-----|---------------|
| 1 | 50017 | Collar | 1 | | 37 | | Split pin | 1 | ϕ 2.5x16 |
| 2 | | Hex. socket head bolt | 2 | M6x20 | 38 | 18-80031 | Bolt | 1 | |
| 3 | 50026 | Cap collar | 2 | | 39 | 18-80030 | Pin | 1 | |
| 4 | | Thrust bearing | 2 | NTB/AS2 1226 | 40 | 18-80019 | Block | 2 | |
| 5 | 80005 | Yoke Plate | 1 | | 41 | 18-80016 | Nut | 1 | |
| 6 | | Nut | 1 | M10 | 42 | 18-80018 | Block | 1 | |
| 7 | | Flat hexagon screw | 4 | M6x8 | 43 | 18-80015 | Screw | 1 | |
| 8 | 80002 | Cover plate | 1 | | 44 | 18-80014 | Knob | 1 | |
| 9 | 80004 | Yoke | 1 | | 45 | 18-80028 | Bolt | 1 | |
| 10 | 18-70083 | Copper pin | 3 | | 46 | | Set screw | 4 | M6x12 |
| 11 | | Set screw | 3 | M8x16 | 47 | 18-80021 | Bracket | 1 | |
| 12 | | Hex. socket head bolt | 4 | M8x45 | 48 | 18-80020 | Eccentric pin | 1 | |
| 13 | | Taper pin | 2 | #6x1 1/2"L | 49 | | Hex. socket head bolt | 2 | M10x50 |
| 14 | 15-80001 | Main bracket | 1 | | 50 | 80027 | Bracket | 1 | |
| 15 | 18-80003 | Plate | 1 | | 51 | 18-80023 | Hub | 1 | |
| 16 | | Done cross screw | 2 | M6x10 | | | | | |
| 17 | | Set screw | 3 | M8x25 | | | | | |
| 18 | | Hexagon nut | 3 | M8 | | | | | |
| 19 | | Hex. socket head bolt | 2 | M8x30 | | | | | |
| 20 | | Rivet | 4 | ϕ 2 | | | | | |
| 21 | 15-80025 | Name plate | 1 | | | | | | |
| 22 | | Hex. socket head bolt | 2 | M8x20 | | | | | |
| 23 | 18-80033 | Stop | 2 | | | | | | |
| 24 | 15-80010 | Plate | 1 | | | | | | |
| 25 | 18-80017 | Nut | 1 | | | | | | |
| 26 | 15-80012 | Gib | 1 | | | | | | |
| 27 | | Hex. socket head bolt | 3 | M6x30 | | | | | |
| 28 | 18-80011 | Slide pivot pin | 1 | | | | | | |
| 29 | | "O" ring | 1 | P21 | | | | | |
| 30 | 18-80006 | Side block | 1 | | | | | | |
| 31 | 80008 | Gib | 1 | | | | | | |
| 32 | 80007 | Screw | 1 | | | | | | |
| 33 | | Hex. socket head bolt | 2 | M8x25 | | | | | |
| 34 | 15-80009 | Swive slide | 1 | | | | | | |
| 35 | | Hex. socket head bolt | 2 | M6x25 | | | | | |
| 36 | 15-80024 | Name plate | 1 | | | | | | |


2009.08

-M03-

BED STOP




BED STOP



[illegible]


Page 1/1

BED STOP
MICROMETER BEDSTOP



SED STOP

MICROMETER BEDSTOP




ERL-13-15


Page 1/1

[illegible]

STATIONERY STEADY




STATIONERY STEADY




ERL-13-16

[illegible]

TRAVELLING STEADY




TRAVELLING STEADY




ERL-13-17

[illegible]

CHIP COVER



CHIP COVER



ERL-13-18

Page 1/1

[illegible]